

# INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 07.06.2022		District: Kaimur (Bhabhua)
Division : Bhabhua		Length (km): 1.9
Name of the Road: Khairi to Dhasa (Lohra)		
Scheme/Programme: MMGSY		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	<b>Pavement</b>	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
e)	Contraction Joints provided or not (CC Pavement)	S
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- found satisfactory		
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	S
Observation Remarks:- found satisfactory		
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- Satisfactory		
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:- Kumar Rakesh

Designation:- T.A. RWD Patna circle

*[Signature]*  
7-06-22  
R.E.

(Signature)

*[Signature]* 07.06.22  
तकनीकी सलाहकार  
ग्रामीण कार्य विभाग  
कार्य अंचल, पटना