## INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection: 6/6/22 District: Kalmur (Bhabhua)		
Division: Bhabua Length (km): 1.6		
Name of the Road: L095 to Lohara		
Scheme/Programme: MMGSY		
SI. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
e)	Contraction Joints provided or not (CC Pavement)	
f)	Compaction of flank/slope & raincuts if any	8
Lound Saturfactory		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	*
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	
	Condition of Vent Clearance	
Observation Remarks:-		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:- found Salas Jactory		
4.	Compliance History	
(a)	Status of ATR's & any others	-
Overall Rating :  Satisfactory (S)/ Unsatisfactory (U)		

Name of Officer:- Kurnar Rakesh Designature:- T.A. RWD Patry Circle

(Signature) मीण कार्य विभाग कार्य अंचल, पटना

Blum 06/6/122 A'C