INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection: 05-06-2022 District: Kainur			
Division: Bhabhua Length (km): 1,550 Km			
Name of the Road: TO2 to Nauhatta Harijan Tola.			
Scheme/Programme: MMGrS Y			
Sl. No.	Parameters to be checked Remarks (S/U		Remarks (S/U)
1.	Pavement		
a)	Condition of Surfacing		S
b)	Riding Quality		S
c)	Road Camber		S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		-
e)	Contraction Joints provided or not (CC Pavement)		
f)	Compaction of flank/slope & raincuts if any		S
Observation Remarks:-			
found Satisfactory			
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		•
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridges		
d)	Condition of Vent Clearance	_	
Observation Remarks:-			
3.	Road Furniture		
	Whether sign boards/informatory/cau stones/Pavement road markings are pro	ntionary Board/ km & 200m ovided and maintained	S
Observation Remarks:-			
found Satrofactory			
4,	Compliance History	v	
a) (Status of ATR's & any others		-
Overall Rating : Satisfactory (S)/ Unsatisfactory (U) :			
19.		, satisfactory (U)	3

Name of Officer:- Kumar Rakesh Designature:- T.A. RWD Patra circle

तकनीकी सलाहकार (Signatune) जार्व विभाग कार्य अंचल, परना

