## INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of	Inspection: 8/06/2021 District: 60		The State of the S
Division	n: BIKRAMGUNJ Length (km):	C. Wer.	
Name o	of the Road: PWD ROAD BIKRAMGUNI TO	CEMEN	ADHO PUR
Scheme	Programme: MMGSY NEW MAINTHUE	ALL BOIL	
St. No.	Parameters to be checked		Remarks (S/U)
l.	Pavement		
a)	Condition of Surfacing		5
b)	Riding Quality		S
c)	Road Camber		5
d)	Whether free from defects such as visible cracaggregates in case of CC Pavement.	ks, exposed	
e)	Contraction Joints provided or not (CC Pavement)		
f)	Compaction of flank slope & raincuts if any		S
Observa	ation Remarks:-		
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts includin	g its painting	5
b)	Condition of Abutment & Wing walls, Slab in RCC cul	verts	-
c)	Condition of railings slab/approach for Bridges		
d)	Condition of Vent Clearance		S
Observa	ation Remarks:-		
3.	Road Furniture		
a)	Whether sign boards informatory/cautionary Board/ stones/Pavement road markings are provided and maint	km & 200m ained	5
Observa	ation Remarks:-		
4.	Compliance History		
a)	Status of ATR's & any others		NO
Overal	Rating Satisfactory (S)/ Unsatisfactor	y (U)	SATISFACTOR
Name o	of Officer: Son Kant Prosed.		3/3
Design	ature:- EE	(Sign	lature)
	Vakash Kumar 8/c/2020		

PE