

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :-

Jhanjharpur

Name of Road :-

4021-T05SH52 to Bhagool (V.R. 21) Road

A. For Road

1. Damage Location Chainage :-
2. Damage Length :- 23.20 mtr.
3. Nature of Damage :- 23.20 mtr.
4. Details of Restoration Works

- i. Materials being used in restoration works:-
- ii. Equipment's/Tools being used in Restoration works:-
- iii. Procedure taken up in Restoration works:-
- iv. Restored Length:-

Boiler Pumps
23.20 mtr Tractor & JCB
86.58 m³


B. For Bridge

1. Damage Location Chainage :-
 2. Damage Length :-
 3. Nature of Damage :-
 4. Details of Restoration Works
- i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-

— S —


Signature of JE/AE/EE


20/4/22
ER


Signature
(Name of Inspection)

To S H S 2 to Bhaurai

Schedule XLV-Form No. 134

FDR

Executive Engineer
Rural Works Department
Works Division, Jhanjharpur

DIVISION

JHANJHARPUR

SUB-DIVISION

3118

MEASUREMENT BOOK

10.06.2022
AD

Scanned with CamScanner