

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Jhanjharpur

Name of Road :- Pat Ghat Biraul Path to Lokn Yaduvoh.

A. For Road


1. Damage Location Chainage :- C-11. 250 m to 400 m
2. Damage Length :- 61 m
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:- Brick bats
 - ii. Equipment's/Tools being used in Restoration works:- Tractor.
 - iii. Procedure taken up in Restoration works:- 54.54 m
 - iv. Restored Length:-


B. For Bridge

1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

C. Requirement of New CD/ Bridges

- i. Name of Road:-
- ii. Location Chainage:-
- iii. Type of CD Work/ Length required:-


Signature /EE


Signature
(Name of Inspection)

Paitghat Borsaul Path to Lokna Yadav to (FDR)

Shedule XLV Form No. 134.

Executive Engineer
Rural Works Department
Works Division, Jhanjhar

DIVISION

JHANJHARPUR

SUB-DIVISION

3119

Measurement Book


(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	CH	-	FDR		
Name of work:-	Motorable road from Paitghat.				
	Birend path to Lohm				
	yadav to				
Agency :-					

[illegible]

Scanned with CamScanner

Sch. XLV-Form No. 134

Sch. XLV-Form No. 134					Contents of area
Particulars	Details of actual measurement				
	No.	L.	B.	D.	
Abstract of cost					
①	P/v & filling brick bak in ditches/damaged embankment				
54.545 m ³ @ 1/4 wide T.M. @ 1/1					
54.545 m ³ @ Rs 2004.96/m ³					109361.60
ADD 12% GST					Rs 13.123 = 0
ADD 1% L.C					Rs 1094.200
ADD S. Fee 10% 54.545 x 1.82					Rs 5629.200
					129207.200
 11.6.22 J.E.					