




ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

DETAILED PROJECT REPORT FOR FDR



Name of the Road :-

Kanti motipur PMGSY sadak se shine chowk bus stand
to se gopalpur PMGSY path tak sadak marammati

DISTRICT	Muzaffarpur		
DIVISION	Muzaffarpur West		
BLOCK	Kanti		
TOTAL LENGTH OF ROAD	:	2.200	KM
CONSTRUCTION COST	:	0.46 0.534	Lac

Submitted By :-
Executive Engineer
RWD Work Division, Muzaffarpur West

0-576

प्रतिवेदन

कार्य का नाम:- Konli Matipura PMWSY Sadak se shina chark Bus
stand to Jopla PMWSY post पथ में अप्रत्याशित बाढ़/अतिवृष्टि से क्षतिग्रस्त पथ में
यातायात चालू करने हेतु आपातकालीन मरम्मत कार्य।

प्रखण्ड- Konli
वित्तीय वर्ष - 2021-22
प्राक्कलित राशि - Rs. 0.461 Lacs
0.576

प्रस्तुत प्राक्कलन जिसकी प्राक्कलित राशि Rs. 0.461 Lacs है, Konli Matipura PMWSY Sadak
Stand to Jopla PMWSY post प्रखण्ड- Konli में यातायात बहाली हेतु आपातकालीन मरम्मत के
लिए तैयार किया गया है।

अभियंता प्रमुख, ग्रामीण कार्य विभाग, बिहार पटना के पत्रांक 4589 दिनांक 13/11/21 द्वारा
दिये गये निर्देश के आलोक में उक्त पथ के क्षतिग्रस्त पथ में Brick Bats & Local Sand भरकर पथ को चालू
करने का प्रावधान किया गया है। प्राक्कलन वर्तमान चलू अनुसूचित दर पर तैयार किया गया है। इसकी
घटनोत्तर स्वीकृति अपेक्षित है। 44 की डिप्लेटे मर्रा हो है 44 की डिप्लेटे मर्रा हो है 44 की डिप्लेटे मर्रा हो है 44 की डिप्लेटे मर्रा हो है

Shamir
05/11/21

कनीय अभियंता

Raj
05/11/21

सहायक अभियंता

K. S. S. S.
05/11/21

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल -

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- EE PWD muz - west

2 Name of Block/Road :- Kanti

(A) For Road:

1. Damage Location/Chainage :-

2. Damage Length :- 15m

3. Nature of Damage :- This road is damaged by floods 11/12/2021

4. Details of Restoration Works :-

(i) Material being used in Restoration works:- Bricks 100-150, Gabbish 4.49m² and 6m² - Bamboo - 178 nos

(ii) Equipment's/Tools being used in Restoration works:- Pallet, Tippet, Tractor, NP-3 MP - 2.5 cm

(iii) Procedure taken up in Restoration works:- etc

(iv) Restored Length :- 15m

(B) For Bridge:

This is road found by satisfactory

1. Damage Location/Chainage :-

2. Damage Length :-

3. Nature of Damage :-

4. Details of Restoration Works :-

(i) Material being used in Restoration works:-

(ii) Equipment's/Tools being used in Restoration works:-

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length :-

N/A

work found satisfactory

Signature
05-11-2021

201
05/11/2021
AE

Signature of JE/AE/EE

Signature
12.12.21

(Name of Inspection)

GENERAL ABSTRACT

Name of Road Kanti motipur PMGSY sadak se shine chowk bus stand to se gopalpur PMGSY path tak sadak marammati
District Muzaffarpur
Block Kanti
Division Muzaffarpur West
Length of Road (in Km) 2.200 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Sand Filling	0.000
2	Brick Bats	0.346 0.363 0.34829
3	Rubbish	0.042 0.041 0.0428
4	Sand bag	0.070 0.065 0.0703
5	u.p.	0.118 0.054
6	bamboo piles	0.000
	SUB TOTAL	0.576 0.534 0.461
	GRAND SUB TOTAL	0.534 0.461

[Signature]
15/11/21
JE
RWD

[Signature]
05/11/2021
AE
RWD

[Signature]
05/11/21
EE
RWD

As Per S.E. RWD (W) Circle Muz
Letter No 1179 Dated 01/10/2021
Estimate has been verified by inspecting
E.E. RWD. (W) Division Mathura

Technically Sanctioned for Rs. 0.576 lacs
(Rs. Fifty Seven thousand Six hundred) only
(provisionally)

[Signature]
28.12.21
Superintending Engineer
Rural Works Department
Work Circle, Muzaffarpur