



ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

DETAILED PROJECT REPORT FOR FDR



Name of the Road :-	Kharauni More to Amar Vidya Bihar Tak Via Maukundpur Tola Road		
DISTRICT	Muzaffarpur		
DIVISION	Muzaffarpur West		
BLOCK	Paroo		
TOTAL LENGTH OF ROAD	:	2.74 0.000	KM
CONSTRUCTION COST	:	3.47 3.54	Lac

Submitted By :-
Executive Engineer
RWD Work Division, Muzaffarpur West

प्रतिवेदन

कार्य का नाम:- Khavanni More to Amar Village Bihar via Mukulpur Tola

..... पथ में अप्रत्याशित बाढ़/अतिवृष्टि से क्षतिग्रस्त पथ में यातायात चालू करने हेतु आपातकालीन मरम्मत कार्य।

प्रखण्ड- पा 77
वित्तीय वर्ष - 2021-22
प्राक्कलित राशि - Rs. 2.57 लाख
3.447

प्रस्तुत प्राक्कलन जिसकी प्राक्कलित राशि 3.447 लाख है, Khavanni More to Amar Village Bihar via Mukulpur Tola, प्रखण्ड- पा 77 में यातायात बहाली हेतु आपातकालीन मरम्मत के लिए तैयार किया गया है।

अभियंता प्रमुख, ग्रामीण कार्य विभाग, बिहार पटना के पत्रांक 4589 दिनांक 13.11.2021 द्वारा दिये गये निर्देश के आलोक में उक्त पथ के क्षतिग्रस्त पथ में Brick Bats & Local Sand भरकर पथ को चालू करने का प्रावधान किया गया है। प्राक्कलन वर्तमान चलू अनुसूचित दर पर तैयार किया गया है। इसकी घटनोत्तर स्वीकृति अपेक्षित है। पन् की जाँच की गई है, MS की जाँच लगेगी।

15.11.21
कनीय अभियंता

15.11.2021
सहायक अभियंता

15.11.21
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल:-

Inspection Report for Flood Damage Work

Date:- 02.12.2021

1 Name of PIUs :- E.E. R.W.D. Muzaffarpur West.

2 Name of Block/Road :- Paved/16km in More to Amar Bidiya Brihas via Mankudpur Talq.

(A) For Road:

1. Damage Location/Chainage :- 1.50 KM.
2. Damage Length :- 10.00 M.
3. Nature of Damage :- Road Cully by Flood & Heavy rain
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- Bricks Bala & HP 3 H.P-1000mm.
 - (ii) Equipment's/Tools being used in Restoration works:- Road roller.
 - (iii) Procedure taken up in Restoration works:
 - (iv) Restored Length :- 10.00 M.

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

The work found satisfactory

K.A

work found satisfactory

02.12.21
Signature of JE/AE/EE

Signature
02.12.21

(Name of Inspection)

GENERAL ABSTRACT

Name of Road Kharauni More to Amar Vidya Bihar Tak Via Maukundpur Tola Road
District Muzaffarpur
Block Paroo
Division Muzaffarpur West
Length of Road (in Km) 2.71 ~~2.71~~ Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	0.000
2	Brick Bats	3.019 / 3.149
3	Sand Filling	0.094 / 0.091
4	Sand bag	0.000
5	H.P.	0.299
	SUB TOTAL	0.334 / 3.540
	GRAND SUB TOTAL	3.447 / 3.540

15/11/21
JE
RWD

15/11/2021
AE
RWD

15/11/21
EE
RWD

As Per S.E. RWD (W) Circle Muz.
Letter No 1179 Dated 01/10/2021
Estimate has been verified by inspecting
E.E. RWD. (W) Division

Technically Sanctioned for Rs. 3.447 lacs (Rs. Three
lacs forty four thousand Seven hundred) only
(Provisionally)

28/12/21
Superintending Engineer
Rural Works Department
Work. Circle, Muzaffarpur