



ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

DETAILED PROJECT REPORT FOR FDR



Name of the Road :-	PMGSY Road Baijalpur Bangali Paswan ke Ghar to Paras Ray ke Ghar Tak via Baijalpur Paswan Tola West		
DISTRICT	Muzaffarpur		
DIVISION	Muzaffarpur West		
BLOCK	Paroo		
TOTAL LENGTH OF ROAD	:	1.139	KM
CONSTRUCTION COST	:	6.399	Lac

Submitted By :-
Executive Engineer
RWD Work Division, Muzaffarpur West

Geo-tag photo not attached

54
DPR-5

प्रतिवेदन

कार्य का नाम:- P.M.G.S.Y Road Baijapur Bangali Pawan ke Gharo Se Pawan

Road via Baijapur Pawan Tola पथ में अप्रत्याशित बाढ़/अतिवृष्टि से क्षतिग्रस्त पथ में यातायात चालू करने हेतु आपातकालीन मरम्मत कार्य।

प्रखण्ड- Pawan

वित्तीय वर्ष - 2021-22

प्राक्कलित राशि - Rs. 6.198 Lacs

प्रस्तुत प्राक्कलन जिसकी प्राक्कलित राशि 6.198 Lacs है, _____
प्रखण्ड- Pawan में यातायात बहाली हेतु आपातकालीन मरम्मत के लिए तैयार किया गया है।

अभियंता प्रमुख, ग्रामीण कार्य विभाग, बिहार पटना के पत्रांक 4589 दिनांक 13.17.2021 द्वारा दिये गये निर्देश के आलोक में उक्त पथ के क्षतिग्रस्त पथ में Brick Bats & Local Sand भरकर पथ को चालू करने का प्रावधान किया गया है। प्राक्कलन वर्तमान चलू अनुसूचित दर पर तैयार किया गया है। इसकी घटनोत्तर स्वीकृति अपेक्षित है। पन्थ की प्रकृति 2015 में दर्ज है, इसे सच मानें।

12/11/2021
कनीय अभियंता

12/11/2021
सहायक अभियंता

12/11/21
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल:-

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- *EE RWD Muz-West*

2 Name of Block/Road :- *patoo,*

(A) For Road:

1. Damage Location/Chainage :- *0.850km*
2. Damage Length :- *25m*
3. Nature of Damage :- *flood cutting by flood & heavy rain*
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- *Bricks 120 - 273.61m³, Local sand - 37.50m³*
 - (ii) Equipment's/Tools being used in Restoration works:- *Roller, Tipper*
 - (iii) Procedure taken up in Restoration works:
 - (iv) Restored Length :- *25m*
The work found satisfactory

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- *NP-3 1000mm H.B*
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-
work found satisfactory

Signature
SE
Signature of JE/AE/EE

Signature
02.12.21
Signature

(Name of Inspection)

GENERAL ABSTRACT

Name of Road PMGSY Road Baljalpur Bangali Paswan ke Ghar to Paras Ray ke Ghar Tak via Baljalpur Paswan
Tola West
District Muzaffarpur
Block Paroo
Division Muzaffarpur West
Length of Road (in Km) 1.139 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	0.000
2	Brck Bats	5.649 5.892
3	Sand Filling	0.213 0.208
4	Sand bag	0.000
5	H.P.	0.334 0.299
	SUB TOTAL	6.196 6.399
	GRAND SUB TOTAL	6.196 6.399

S. S. 15/11/2021
JE
RWD

P. M. 15/11/2021
AE
RWD

K. M. 11/11/21
EE
RWD

As Per S.E. RWD (W) Circle Muz.
Letter No 1179 Dated 01/10/2021
Estimate has been verified by inspecting
E. E. RWD. (W) Division

*Technically sanctioned for Rs. 6.196 lacs
(Rs. Six Lacs nineteen thousand six hundred) only
(Provisionally)*

28.12.21
Superintending Engineer
Rural Works Department
Work Circle Muzaffarpur
27.12.21