



ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

DETAILED PROJECT REPORT FOR FDR



Name of the Road :- **L040 NH-77 Anandpur Kharauni to Brahampur
Khakhan Rd**

DISTRICT **Muzaffarpur**

DIVISION **Muzaffarpur West**

BLOCK **Paroo**

TOTAL LENGTH OF ROAD : **3.600** KM

CONSTRUCTION COST : **0.87**
-0.903 Lac

Submitted By :-
Executive Engineer
RWD Work Division Muzaffarpur West

प्रतिवेदन

कार्य का नाम:- L090 NH-74 Anandpur / Zharouni to Brahampur / Zharouni.Road

पथ में अप्रत्याशित बाढ़/अतिवृष्टि से क्षतिग्रस्त पथ में यातायात चालू करने हेतु आपातकालीन मरम्मत कार्य।

प्रखण्ड- पारस
वित्तीय वर्ष - 2021-22
प्राक्कलित राशि - Rs. 0.87 (लाख)

प्रस्तुत प्राक्कलन जिसकी प्राक्कलित राशि 0.87 लाख है, L090 NH-74 Anandpur / Zharouni to Brahampur, प्रखण्ड- पारस में यातायात बहाली हेतु आपातकालीन मरम्मत के लिए तैयार किया गया है।

अभियंता प्रमुख, ग्रामीण कार्य विभाग, बिहार पटना के पत्रांक 4589 दिनांक 13.11.2021 द्वारा दिये गये निर्देश के आलोक में उक्त पथ के क्षतिग्रस्त पथ में Brick Bats & Local Sand भरकर पथ को चालू करने का प्रावधान किया गया है। प्राक्कलन वर्तमान चलू अनुसूचित दर पर तैयार किया गया है। इसकी घटनोत्तर स्वीकृति अपेक्षित है। अन्य की प्रवृत्ति 11/15 में यही है। प्रति मन्त्र है।

15/11/21
कनीय अभियंता

15/11/2021
सहायक अभियंता

15/11/21
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल:-

Inspection Report for Flood Damage Work

Date:- 02.12.2021

1 Name of PIUs :- E.E. R.W.D. Muzaffarpur west

2 Name of Block/Road :- Patna/Logonhi-74 Anandpur/Charani to Barahatpur/Chakran

(A) For Road:

1. Damage Location/Chainage :- 0.23 KM.

2. Damage Length :- 14.50 m.

3. Nature of Damage :- Road Culty by Flood & Heavy Rain

4. Details of Restoration Works :-

(i) Material being used in Restoration works:-

(ii) Equipment's/Tools being used in Restoration works:- Road roller

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length :- 14.50 m.

Brids Bafsi-39-150³, Sand-10.88 m³

The work found Satisfactory

(B) For Bridge:

1. Damage Location/Chainage :-

2. Damage Length :-

3. Nature of Damage :-

4. Details of Restoration Works :-

(i) Material being used in Restoration works:-

(ii) Equipment's/Tools being used in Restoration works:-

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length :-

N-A

work found satisfactory

Signature of JE/AE/EE
02.12.21

Signature
02.12.21

(Name of Inspection)

GENERAL ABSTRACT

Name of Road L049 NH-77 Anandpur Kharauni to Brahampur Khakhan Rd

District Muzaffarpur

Block Paroo

Division Muzaffarpur West

Length of Road (in Km) 3.600 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	0.000
2	Brick Bats	0.808 0.843
3	Sand Filling	0.062 0.000
4	Sand bag	/ 0.000
5	H.P.	/ 0.000
	SUB TOTAL	0.870 0.903
	GRAND SUB TOTAL	0.870 0.903

15-11-21
JE
RWD

15/11/2021
AE
RWD

18/11/21
EE
RWD

As Per S.E. RWD (W) Circle Muz
Letter No 1178 Dated 01/10/2021
Estimate has been verified by inspecting
E. E. RWD. (W) Division

*Technically Sanctioned for Rs. 0.87 lac
(Rs. Eighty Seven thousand) only (Provisionally)*

28/12/21
Superintending Engineer
Rural Works Department
Work Circle, Muzaffarpur
27-12-21