




ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

2021-22

FLOOD DAMAGED REPORT






T03 to Nagargama Wast

DISTRICT	:-	Samastipur	
DIVISION	:-	Dalsingh Sarai	
BLOCK	:-	Dalsinghsarai	
TOTAL LENGTH OF ROAD	:-	0.111	KM
TOTAL COST OF PROJECT	:-	3.91	Lac

Site Photograph

Name of Road:- T03 to Nagargama West
Block:- Dalsinghsaral

Distt- Samastipur



gita
02/11/21
J.E.

h
AOS
2.11.21

SUMMARY OF COST ESTIMAT FOR THE PROJECT

NAME OF ROAD :- T03 to Nagargama West

DISTRICT SAMASTIPUR

BLOCK Dalsinghsarai

S.NO	DESCRIPTION	AMOUNT LAKH
1	BAMBOO WORK	33022.62435
2	BRICK BATS	307935.371
3	SAND FILLED BAGS	5000.940
	SUB TOTAL:-	345958.935
	12% GST on Total Amount:-	41515.072
	1% lab cess	3459.589
	Total Cost (including GST and Labour Cess	390933.597

Say 3,90,934=RO

Alinda
02/11/21
Junior Engineer

Chauhan
2.11.21
Assistant Engineer

Chauhan
01.12.21
Executive Engineer

Sanctioned
Provisional Technical approved for Rs 3,90,934=RO Three lakh ninety thousand nine hundred thirty four only Rupees and one paise only. 12% and C.P. 1%,

Chauhan
10.12.21
बसोबास अधिकारी
बसोबास कार्यालय
बसोबास, बसोबास
10/12/21
T.A.

YEAR (2021-2022)
GENERAL ABSTRACT OF COST

BLOCK :- Dalsinghsarai

DISTRICT :- SAMASTIPUR

NAME OF ROAD :- T03 to Nagargama East

S.NO	ITEM OF WORK	AMOUNT
A		Rs. 390934
	TOTAL COST OF CONSTRUCTION	Rs. 390934
	SUB TOTAL	Rs. 390934

Ashta
02/11/21
Junior Engineer

Chadga
2-11-21
Assistant Engineer

Alhar
01/12/21
Executive Engineer
RWD, Works Division,
Dalsinghsarai

Technical Party Approved for 3,90,

Inspection Report for Flood Damage Work

Date.:

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Dalsinghgarh

2. Name of Block – Dalsinghsarai

3. Name of Road/Bridge - To3 to Nagaogama West

A. for Road

1. Damage Location/Chainage

25.639966°N
: 25.637444°N

85.803396°E
85.806219°E

2. Damage Length

$$: 0.111 \text{ km}$$

3. Nature of Damage

Heavy rain

4. Details of Restoration Works

i. Material being used in Restoration works :

Buck Bat sand filling bag
'bamboo work'.

ii. Equipments/Tools being used in Restoration Works :

traitor brother

iii. Procedure taken up in Restoration works : —

iv. Restored Length :

0.111 km

B. for Bridge

1. Damage Location/Chainage

—

2. Damage Length

1

3. Nature of Damage

10

4. Details of Restoration Works

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :

iv. Restored Length :

Ashta
08/04/22
J.E.

A.E.

Executive Engineer,
R.W.D. Works Division,
.....
.....

Wanda G. Heston

Signature
Date 5/14/22.

(Name of Inspector)
E. G. T...
R. D. W. H. S. ...