



ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

DETAILED PROJECT REPORT FOR FDR

YEAR-2021-22



Name of the Road :-

Restoration of Road from sahebganj Road me
Transformer ke Nikat to Khajurahi Pul Tak

DISTRICT

Muzaffarpur

DIVISION

Muzaffarpur West

BLOCK

Motipur

TOTAL LENGTH OF ROAD

:

0.000

KM

CONSTRUCTION COST

:

~~0.696~~

Lac

0.67

Submitted By :-
Executive Engineer
RWD Work Division, Muzaffarpur West

प्रतिवेदन

कार्य का नाम:- East of Road from Sahabganj Road me Transformer
ke nikal TO Khatu Uchhi'pur पथ में अप्रत्याशित बाढ़/अतिवृष्टि से क्षतिग्रस्त पथ में
यातायात चालू करने हेतु आपातकालीन मरम्मति कार्य।

प्रखण्ड- मोतीपुर

वित्तीय वर्ष - 2021-2022

प्राक्कलित राशि - Rs. 0.696 0.67 lac

प्रस्तुत प्राक्कलन जिसकी प्राक्कलित राशि 0.67
0.696 लाख है, प्रखण्ड- मोतीपुर में यातायात बहाली हेतु आपातकालीन मरम्मति के
लिए तैयार किया गया है।

अभियंता प्रमुख, ग्रामीण कार्य विभाग, बिहार पटना के पत्रांक 4589 दिनांक 13.11.21 द्वारा
दिये गये निर्देश के आलोक में उक्त पथ के क्षतिग्रस्त पथ में Brick Bats & Local Sand भरकर पथ को चालू
करने का प्रावधान किया गया है। प्राक्कलन वर्तमान चलू अनुसूचित दर पर तैयार किया गया है। इसकी
घटनोत्तर स्वीकृति अपेक्षित है। पथ की प्रविष्टि MIS में है। MIS की प्रतीति संलग्न।

S. S. 2021
कनीय अभियंता

A. S. 2021/21
सहायक अभियंता

K. S. 2021/21
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल:-

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :-

2 Name of Block/Road :- *moleper*

(A) For Road:

1. Damage Location/Chainage :-
2. Damage Length :- *15m*
3. Nature of Damage :- *Due to heavy rains & flood*
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- *Bitumen's Bats, Sand filling*
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- *15m*

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

The work found satisfactory.

NA.

work found satisfactory

[Signature]
Signature of JE/AE/EE

[Signature]
Signature of JE/AE/EE

[Signature]
02-12-21
Signature

(Name of Inspection)

GENERAL ABSTRACT

Name of Road Restoration of Road from sahebganj Road me Transformer ke Nikat to Khajurahi Pul Tak
District Muzaffarpur
Block Motipur
Division Muzaffarpur West
Length of Road (in Km) 0.000 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	0.000
2	Brick Bats	0.620
3	Sand Filling	0.011
4	Sand bag	0.000
5	H.P.	0.064
	SUB TOTAL	0.696
	GRAND SUB TOTAL	0.696

0.669
say 0.67 lac

JE
25/11/2021
RWD

AE
25/11/21
RWD

ESM
25/11/21
EE
RWD

As Per S.E. RWD (M) Circle Muz.
Letter No. 1179 Dated 01/10/2021
Estimate has been verified by inspecting
E.E. RWD. (M) Division

Technically Sanctioned for Rs. 0.67 lac
(Rs. Sixty Seven thousand) only (provisionally)

28/12/21
Superintending Engineer
Rural Works Department
Work Circle, Muzaffarpur