



ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

DETAILED PROJECT REPORT FOR FDR

YEAR-2021-22



Name of the Road :-		Restoration of Road from MMGSY to Sahni Tola Bagwara	
DISTRICT		Muzaffarpur	
DIVISION		Muzaffarpur West	
BLOCK		Motipur	
TOTAL LENGTH OF ROAD	:	1.536	KM
CONSTRUCTION COST	:	0.645 0.620	Lac

Submitted By :-
Executive Engineer
RWD Work Division, Muzaffarpur West

MUZAFFARPUR

प्रतिवेदन

कार्य का नाम:- Restoration of Road from MMBSY to Sahni Tola.

Bagwara पथ में अप्रत्याशित बाढ़/अतिवृष्टि से क्षतिग्रस्त पथ में यातायात चालू करने हेतु आपातकालीन मरम्मत कार्य।

प्रखण्ड- कौशल्या

वित्तीय वर्ष - 2021-22

प्राक्कलित राशि - Rs. 0.646 0.620 ✓

प्रस्तुत प्राक्कलन जिसकी प्राक्कलित राशि 0.620 है, 0.646 मिला है, _____

प्रखण्ड- कौशल्या में यातायात बहाली हेतु आपातकालिन मरम्मत के लिए तैयार किया गया है।

अभियंता प्रमुख, ग्रामीण कार्य विभाग, बिहार पटना के पत्रांक 4589 दिनांक 13.11.21 द्वारा दिये गये निर्देश के आलोक में उक्त पथ के क्षतिग्रस्त पथ में Brick Bats & Local Sand भरकर पथ को चालू करने का प्रावधान किया गया है। प्राक्कलन वर्तमान चलू अनुसूचित दर पर तैयार किया गया है। इसकी घटनोत्तर स्वीकृति अपेक्षित है। उपरोक्त प्रकृति मिस में है। मिस की प्रति संलग्न

[Signature]
कनीय अभियंता

[Signature]
सहायक अभियंता

[Signature]
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल:-

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- E.E. R.W.D. Muz. West.

2 Name of Block/Road :- Motipur - MMGS 7 to Sahni Tola Bagwara.

(A) For Road:

1. Damage Location/Chainage :-

2. Damage Length :- 10m

3. Nature of Damage :-

4. Details of Restoration Works :- Brick Bat and Sand filling

(i) Material being used in Restoration works:- Brick Bat and Sand

(ii) Equipment's/Tools being used in Restoration works:-

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length :- The work is found satisfactory.

(B) For Bridge:

1. Damage Location/Chainage :-

2. Damage Length :-

3. Nature of Damage :-

4. Details of Restoration Works :-

(i) Material being used in Restoration works:-

(ii) Equipment's/Tools being used in Restoration works:-


(iii) Procedure taken up in Restoration works:-

(iv) Restored Length :-

NA

The work is found satisfactory


Signature of JE/AE/EE


13/12/21
Signature

(Name of Inspection)

GENERAL ABSTRACT

Name of Road Restoration of Road from MMGSY to Sahni Tola Bagwara

District Muzaffarpur

Block Motipur

Division Muzaffarpur West

Length of Road (in Km) 1.536 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	0.000
2	Brick Bats	0.625 0.599
3	Sand Filling	0.021 0.021
4	Sand bag	0.000
5	H.P.	0.000
	SUB TOTAL	0.646 0.620
	GRAND SUB TOTAL	0.646

JE
RWD

AE
RWD

EE
RWD

As Per S.E. RWD (W) Circle Muz.
Letter No. 1179 Dated 01/10/2021
Estimate has been verified by inspecting
E.E. RWD. (W) Division

Technically Sanctioned for Rs. 0.62 lac
(Rs. Sixty two thousand) only (provisionally)

Superintending Engineer
Rural Works Department
Work Circle, Muzaffarpur