




ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

2021-22

FLOOD DAMAGED REPORT



Railway Gumti Raipur Balari Path to Mushari

TRICT	:-	Samastipur	
ISION	:-	Dalsingh Sarai	
OCK	:-	Ujiarpur	
AL LENGTH OF ROAD	:-	0.245	KM
AL COST OF PROJECT	:-	8.30	Lac

OK

Site Photograph

Name of Road:- Railway Gumti Raipur Balari Path to Mushari
Block:- Ujiarpur

Distt- Samastipur



Belari Halt, Belari, Bihar 848132,
India
Latitude Longitude
25.819800° 85.799783°
LOCAL 13:43:12 MONDAY 11:01:2021
GMT 08:13:12 ALTITUDE 4 METER



Ram pukar Ward no 2, Belari,
Bihar 848132, India
Latitude Longitude
25.818002° 85.797804°
LOCAL 13:45:15 MONDAY 11:01:2021
GMT 08:15:15 ALTITUDE 22 METER



Belari Halt, Belari, Bihar 848132,
India
Latitude Longitude
25.819819° 85.799772°
LOCAL 13:43:26 MONDAY 11:01:2021
GMT 08:13:26 ALTITUDE 22 METER

YEAR (2021-2022)
GENERAL ABSTRACT OF COST

DCK

Ujjainpur

DISTRICT :- SAMASTIPUR

E OF ROAD :- Railway Gumti Raipur Balari Path to Mushari

NO	ITEM OF WORK					AMOUNT	
A							
	TOTAL COST OF CONSTRUCTION				:-	Rs.	830782
				SUB TOTAL	:-	Rs.	830782

[Signature]
5/11/2021

Junior Engineer

[Signature]
5/11/21

Assistant Engineer

Executive Engineer
RWD, Works Division,
Dalsinghsarai

SUMMARY OF COST ESTIMAT FOR THE PROJECT

NAME OF ROAD :- Railway Gumti Raipur Balari Path to Mushari

DISTRICT

SAMASTIPUR

BLOCK

Ujiarpur

S NO	DESCRIPTION	AMOUNT LAKH
1	Earth Work	60484.05
2	BrickBats	674721.394
	SUB TOTAL:-	735205.444
	12% GST on Total Amount:-	88224.653
	1% lab cess	7352.054
	Total Cost (including GST and Labour Cess	830782.151

[Signature]

Junior Engineer

[Signature]
5/11/21

Assistant Engineer

[Signature]
2.12.21

Executive Engineer

Sanctioned Provisional Technical work approved for Rs 8,30,782 = 00 Say Eight Lakh thirty thousand Seven Hundred and Eighty two only including O.H.C. &c. Contractor prohibit 10%.

[Signature]
10/12/21
T.A.

[Signature]
10.12.21

प्रमुख कार्य
प्रमुख कार्य निष्पाद
कार्य प्रमुख, प्रमुखी

[Signature]
AC
10/12/21

Inspection Report for Flood Damage Work

Date: 5.4.22

1. Name of PIUs - Executive Engineer, R.W.D., Works, Division, Dalsingpur
2. Name of Block - urison for
3. Name of Road/Bridge - Reidling guri Reidling Belari path to mishi

A. for Road

1. Damage Location/Chainage : - 25.818092, 85.797894, 25.89819
2. Damage Length : 85.797894
3. Nature of Damage : do to rain cut
4. Details of Restoration Works : Earth work, bitu bark
i. Material being used in Restoration works :
ii. Equipments/Tools being used in Restoration Works :
iii. Procedure taken up in Restoration works :
iv. Restored Length :

B. for Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
i. Material being used in Restoration works :
ii. Equipments/Tools being used in Restoration Works :
iii. Procedure taken up in Restoration works :
iv. Restored Length :

5/4/22
J.E.

5/4/22
A.E.

5.04.22
Executive Engineer,
R.W.D. Works Division,
Dalsingpur

Wong dan Co's to
Urson
5/4/22
Signature
(Name of Inspector)
E.E. Tushing
RWD MMS Dalsingpur