

ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

DETAILED PROJECT REPORT FOR FDR

BIHAR



of the Road:-

Bhagwanpur to kushi path

CT	Muzaffarpur
DN	Muzaffarpur West
	Kanti
LENGTH OF ROAD	: 2.700 KM
RUCTION COST	: 15.456 26.422 Lac

Submitted By :-
Executive Engineer
RWD Work Division, Muzaffarpur West

15.901

प्रतिवेदन

कार्य का नाम:-

Bhagwanpur to kushi path

.....पथ में अप्रत्याशित बाढ़/अतिवृष्टि से क्षतिग्रस्त पथ में यातायात चालू करने हेतु आपातकालीन मरम्मत कार्य।

प्रखण्ड- Konki

वित्तीय वर्ष - 2021-22

प्राक्कलित राशि - Rs. 15.95L 15.901

15.901

प्रस्तुत प्राक्कलन जिसकी प्राक्कलित राशि Rs. 15.95L 15.901 है, Bhagwanpur to Kushi path, प्रखण्ड- Konki में यातायात बहाली हेतु आपातकालीन मरम्मत के लिए तैयार किया गया है।

अभियंता प्रमुख, ग्रामीण कार्य विभाग, बिहार पटना के पत्रांक 4589 दिनांक 13/11/21 द्वारा दिये गये निर्देश के आलोक में उक्त पथ के क्षतिग्रस्त पथ में Brick Bats & Local Sand भरकर पथ को चालू करने का प्रावधान किया गया है। प्राक्कलन वर्तमान चलू अनुसूचित दर पर तैयार किया गया है। इसकी घटनोत्तर स्वीकृति अपेक्षित है। 421 की ड्रिफ्टी काम में है जिसकी प्रति संलग्न है जिसका & NO- 25 है।

Abhimata
05-11-2021

कनीय अभियंता

Boi
05/11/2021

सहायक अभियंता

Kom
05/11/21

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल:-

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- *EE RND Muz was A*

2 Name of Block/Road :- *kmli / Bhagwanpur to Kusi Path*

(A) For Road:

1. Damage Location/Chainage :-
2. Damage Length :- *545 M*
3. Nature of Damage :- *Heavy rain & Flood*
4. Details of Restoration Works :-
(i) Material being used in Restoration works:- *639.66 MS, 285.16 MS, Brick Bat & Rubish*
(ii) Equipment's/Tools being used in Restoration works:- *Tipper, Tractor, Roller etc*
(iii) Procedure taken up in Restoration works: -
(iv) Restored Length :- *545 M*

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
(i) Material being used in Restoration works:-
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length :-

N/A

work found satisfactory

*As per order
05-11-21*

Signature of JE/AE/EE

Shreyas

12-12-21

Signature

(Name of Inspection)

<u>GENERAL ABSTRACT</u>	
Name of Road	Bhagwanpur to kushl path
District	Muzaffarpur
Block	Kanti
Division	Muzaffarpur West
Length of Road (in Km)	2.700 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Sand Filling	0.000
2	Brick Bats	13.206 13.824
3	Rubbish	2.695 2.601
4	Sand bag	0.000
5	H.P.	0.000
6	bamboo piles	0.000
	SUB TOTAL	16.422
	GRAND SUB TOTAL	16.422

15.901 Laws

Abnormal
05-11-07

201
09/12/21

K18m
05/11/24

As Per S.E. RWD (W) Circle Muz
Letter No 1179 Dated 01/10/2021
Estimate has been verified by inspecting
E. E. RWD. (W) Division *Nahua*

Technically sanctioned for Rs. 15.901 lacs
(Rs. Fifteen lacs ninety thousand one hundred)
only (provisionally)

Superintending Engineer
Rural Works Department
Work Circle, Muzaffarpur

$$\frac{28.12.21}{\text{purple}}$$