गामीण कार्य विभाग, कार्य प्रमंडल, सिकहरना, ढाका। पत्रांक - 823 / सिकहरना, ढाका, दिनांक-16.06.2022

प्रेषक :-

कार्यपालक अभियंता, ग्रामीण कार्य विभाग, कार्य प्रमंडल, सिकहरना, ढाका।

सेवा में.

अपर मुख्य कार्यपालक पदाधिकारी, ग्रामीण कार्य विभाग, विश्वसरैया भवन, पाच्वा तल्ला, बिहार, पटना।

विषय :- M/R (3054) New Maintenance Police 2018 योजना हेतु आवंटन अधियाचना के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में सूचित करना है कि इस प्रमंडलान्तर्गत M/R (3054) New Maintenance Police 2018 योजना के अधीन कराये गये कार्य के विरुद्ध भुगतान हेतु आवंटन अधियाचना विहित—प्रपत्र में संलग्न कर समर्पित किया जाता है। अनुलग्नक :— यथोक्त।

विश्वासभाजन

कार्यपालक अभियंता, ग्रामीण कार्य विभाग, कार्य प्रमंडल, सिकहरना, ढाका।

(See Government of Indian's Decision (1) below Rule-150) Form of Utilization Certificate Upto the Month of upto......

PIU:- EE RWD (W) DIVISION DIVAKA

SI.	Name of the	Som DIVISION DHAKA		
	Scheme	Sanction No. & Date with Amount (Rs. In Lakh)	Amount Received (Rs. In	Particulars
	Construction of Rural Roads Under MR-3054		Lakh)	Certified that out of R Nil Lacs received to year 2022-23 in favor Executive Engineer R.W.D. (W), Division Dhaka a sum of Rs N lacks has been utilized for the purpose of MR-305 Schemes as given in the margin for which it was sanctioned of Rs.N
		Γotal :-		Remaining unutilized at the end of the periounder.

Certified that I have satisfied my self that the condition on which the grants-in-aid was sanctioned have been duly fulfilled are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Divisional Account Officer

R.W.D. (W) Div., Dhaka

Kind of Checks Exercised :-

- (i) Works have been supervised by Executive Engineer/Superintending Engineer.
- (ii) Periodical inspection has been conduct by Executive Engineer/Superintending Engineer.
- (iii) Construction material have been tested.
- (iv) Measurement have been recorded in the MBs and test check conducted by the Assistant.
- (v) All other codal Formalities have been observed.

Physical Progress achieved :-

- (i) Construction of Road Works.
- (ii) Construction of CD Works.

Executive Engineer

R.W.D.(W) Div., Dhaka

1	STANDARD FORMATE FOR ROAD Rural Works Deparetment Works Division Dhaka Name Of Road										
Mary Cons			ipahi Domtoli To Sekhauna P	ath							
	Batch No.	RM/EA/SIK/19/0005									
3	Project ID	10108808									
4	Total Length Of Road(in Km)	1.4									
5	Lenth Of Road To Meet Required Service Level [Completed Length] (in Km) [1]		1.4								
6	NO. of Total Quarter (ie 3 Months as a unit) in 5 year	20									
7	Ordinary Maintenance Cost as per Schedule [Agreement Amount For Maintenance] (in Lakh)	13.97668									
8	Quaterly Payment : 1/20 of Ordinary Maintenance Cost as per Schedule (in Lakh) [2]	0.69883									
Compliance Criteria	Standard Job Description	Length Non- Compliant [3]	n- Compliance Weighted Value for Payment Reduction (%) [4]	Reduction Payment [60]=[3]/[1]*[2]*[4]							
- 1	PAVED ROADS AND (CARRIAGEWAY)	0	60%	0							
11	SHOULDERS AND EMBANMENTS	0	10%	0							
III	CROSS DRAINAGE INCLUDING CULVERTS AND BRIDGE	0	15%	0							
IV		0	10%	0							
V	SIGNAGE AND ROAD SAFETY	0	5%	0							
OTAL PAY	MENT REDUCTION FOR THE QUARTER (in Lakh)	[5]		0							

date of Inpection by E/I Or His Agent Prepared by Contractor's Self Control Unit

Name and Designation of person inspecting road

Signature of person inspecting road

J.E

(Signature)

Certify by E/I [Signature] date

Concreate pavement Other activities OM200 Shoulder Unsealed Shoulder OM201 (a) Edge Drop-off (b) Roughness, Scouring (c) Holding water OM202 Embankment Repair OM300 Other activities (Rain Cuom300 Om301 Surface Drains & Verge OM302 Culvert Cleaning															106 Digouts	105 Edge Repair	© Crocodile	(b) Bleeding /	OM104 (a) Loss of Ag	Surface Trea	OM103 Crack Sealing	OM102 Surface Depression	OM101 Pothole Patching	OM100 Sealed payment		No standard Of	2 7	ahi	Rural Works Department	OM01	RWD, Works Division Dhaka	
Digouts Concreate pavement Other activities Shoulder Unsealed Shoulder (a) Edge Drop-off (b) Roughness, Scouring or Potholes (c) Holding water Embankment Repair Other activities (Rain Cuts) Other activities (Rain Cuts) Drainage including culverts major Surface Drains & Verge Culvert Cleaning	avement ies oulder o-off s, Scouring or Potholes vater Repair es (Rain Cuts) luding culverts major luding culverts major	avement ies oulder o-off s, Scouring or Potholes vater vater es (Rain Cuts) luding culverts major luding culverts major	avement ies oulder oulder s, Scouring or Potholes vater es (Rain Cuts) luding culverts major	Cuts)	ring or	ent ouring or	ent ouring or		avement ies oulder	avement ies	avement ies	avement	avement				1.	Flushing	of Agreegate (SurfacebRavelling)	Treatment	8	ression and Rut patching	ching		Name	Work I	1.400 09-08-2021 To 08-11-2021 WD Sub Division : Bankatwa	Domtoli To Sekhauna Path	lent		Requi:	
M ₃ M ₃ Im Im m ₂	No Im Im Im	Lm Lm Lm	Lm Lm	m ₂	Lm Lm	m ₂	m ²	Lm m2	m ₂					3	m ₃	m ²	m ²	m ₂	m ²		E I	m3	m ²	Cille	Unit	Work					sition Formet for Sc	
Nil	Nii Nii N.A	N.A Nil	Nii Nii	Nil Nil	Nil 59.06	Nii Nii	N.		Z.	275.625				N.A	N.A	Nii	Nii	Z.	32.813		1400	0.098	32.813		1						Scheme Head-	
N. N	Nii N.A	N.A			N.	N	2	N.i	N.I.	Zii				N.A	N.A	Z	Nii	Z.	Z		Z.	Z.	Z.		2				SUMMARY	(3)	Head-MR-(3054) Under Bihar	
		STORY OF THE PARTY																							3 4	C.		To:-	OF ORDINARY MAINT	(3rd Quarter)	nder Bihar Rurak	
																		*								Unit OF Required	Position :-	Executive t RWD, Wor	MAINTENANCE		Road Maintenance	
																									6	Required in each Kilo	A.E	Executive Engineer RWD, Works Division Dhaka	INSPECTION		nance Policy-2018	
								Selling Annual Property of the Parket Propert																	7	Kilometere		haka	REPORT			
	The Part of the Pa																								8						(Initial Rectification	
																									9						and Surface f	
THE REAL PROPERTY.				STATE OF THE STATE																					10			Date:			Renewal)	
Defects Rectified within stipulated time Not Required	Defects Rectified within stipulat			Not Required	Not Keduired		Defects Rectified within stipulated time	No Holding Water Found	Not Required	Defects Rectified within stipulated time						No Edge Repair Required	No Crocodile Cracking Found	'No Bleeding/ Flushing Required	Defects Rectified within stipulated time		Defects Rectified within stipulated time	Defects Rectified within stipulated time	Defects Rectified within stipulated time		Comments							

Satis Dens	No No No Name OM400 Vegetation Grass Control (a) Roadside- General Tidy and roadside furniture Tree and Shrub Management Cutting Of Branches Of Trees Cutting Of Shrubs From Road Way OM500 Safety Signage and Road OM501 Signs Maintanence OM503 Distance Stones OM504 Road Marking Other activities Other activities Other activities
06/06/2022 Appendix	Work
Executive Engineer, Works Division, Dhaka	ach Kilometere 6 7 8 9 10 Comments Not Required