




ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

DETAILED PROJECT REPORT FOR FDR



Name of the Road :-		Kotwara Chowk PMGSY Road to Dakshin Mohammadpur Village Tak	
DISTRICT		Muzaffarpur	
DIVISION		Muzaffarpur West	
BLOCK		Paroo	
TOTAL LENGTH OF ROAD		:	0.300 KM
CONSTRUCTION COST		:	9.379 9.774 Lac

Submitted By :-
Executive Engineer
RWD Work Division, Muzaffarpur West

प्रतिवेदन

कार्य का नाम:- Kotdwara Chowk Panchayat road to Maheshpur
Mohamonalpur village पथ में अप्रत्याशित बाढ़/अतिवृष्टि से क्षतिग्रस्त पथ में यातायात चालू करने हेतु आपातकालीन मरम्मत कार्य।

प्रखण्ड- Parro
वित्तीय वर्ष - 2021-22
प्राक्कलित राशि - Rs. 9.379 lacs

प्रस्तुत प्राक्कलन जिसकी प्राक्कलित राशि 9.379 lacs है, प्रखण्ड- Parro में यातायात बहाली हेतु आपातकालीन मरम्मत के लिए तैयार किया गया है।

अभियंता प्रमुख, ग्रामीण कार्य विभाग, बिहार पटना के पत्रांक 4589 दिनांक 13.11.2021 द्वारा दिये गये निर्देश के आलोक में उक्त पथ के क्षतिग्रस्त पथ में Brick Bats & Local Sand भरकर पथ को चालू करने का प्रावधान किया गया है। प्राक्कलन वर्तमान चलू अनुसूचित दर पर तैयार किया गया है। इसकी घटनोत्तर स्वीकृति अपेक्षित है। पथ की प्रत्येक मीटर में दर्ज है, प्रति सलगन है।

15/11/2021
कनीय अभियंता

15/11/2021
सहायक अभियंता

15/11/2021
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल:-

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- *EE Road works DIV muz west*

2 Name of Block/Road :- *PAROO*

(A) For Road:

1. Damage Location/Chainage :- *0.6 km*
2. Damage Length :- *18 m*
3. Nature of Damage :- *Road damage by Flood & Heavy rain*
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- *Brick's ball, 448.33 m, sand - 24800 m³*
 - (ii) Equipment's/Tools being used in Restoration works:- *Roller, Tipper*
 - (iii) Procedure taken up in Restoration works:
 - (iv) Restored Length :- *18 m*

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

The work is not satisfactory

N/A

The work is not satisfactory

S/3/11/2021
Signature of JE/AE/EE

S. Raja
02-12-21
Signature

(Name of Inspection)

Name of Road Kotwara Chowk PMGSY Road to Dakshin Mohammadpur Village Tak

District Muzaffarpur

Block Paroo

Division Muzaffarpur West

Length of Road (in Km) 0.300 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	0.000
2	Brick Bats	9.256
3	Sand Filling	0.123
4	Sand bag	/
5	H.P.	0.000
	SUB TOTAL	9.379
	GRAND SUB TOTAL	9.379
		9.37,854

Signature
JE
15/11/2021

RWD

Signature
AE
15/11/2021

AE

RWD


Signature
EE
15/11/21

EE

RWD

As Per S.E. RWD (W) Circle Muz
Letter No 1179 Dated 01/10/2021
Ess note has been verified by inspecting
E. E. RWD. (W) Division

Technically Sanctioned for Rs. 9.379 lacs
(Rs. Nine lacs thirty seven thousand
nine hundred) only (provisionally)


26.12.21
Superintending Engineer
Rural Works Department
Work Circle, Muzaffarpur


27.12.21