

Inspection Report for Flood Damage work

Date:-

- 1 Name of PIUS :- Madhepura.
2 Name of Block :- Singhpur
3 Name of Road :- Temporary Restoration of Road from Barhri NH106 Se
Babhani path mahuli

A. For Road

- 1 Damage Location/Chainage :-
2 Damage Length :- 0.858 km
3 Nature of damage :- heavy rain fall.
4 Details of Restoration Works :-
i Material being used in Restoration works:- Bitum. Mats, e-bag,
ii Equipments/Tools being used in Restoration works :- Grader, J.C.B. etc.
iii Procedure taken up in Restoration works :-
iv Restored Length :- 0.858 km.

B. For Bridge

- 1 Damage Location/Chainage :-
2 Damage Length :-
3 Nature of damage :-
4 Details of Restoration Works :-
i Material being used in Restoration works:-
ii Equipments/Tools being used in Restoration works :-
iii Procedure taken up in Restoration works :-
iv Restored Length :-

Asst. Secy
01/11/2021
JE

01/11/2021
AE

01/11/2021
EE

01/11/2021

Signature
(Name of inspector)

MB No-1578

Schedule XLV-Form No. 134

Madheburra

DIVISION

Singheshwara

SUB-DIVISION

MEASUREMENT BOOK

Barhara NH106 to Bahani path
Mauli

1st on A/c BM)

1

Name of work.
 Situation of work.
 Agency by which work is executed.
 Date of measurement.
 No. and date of agreement.
 (These four lines should be repeated at the commencement of the measurement relating to each work).

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work:- Restoration of Road from Badheri NH106 to Badheri path Mahuli -					
Agency - Rasthnan Jan Yashni					

Calculation of measurement

72	1x	7x	2x	0.30	4.20m ²
40.00	1x	4x	1.5x	0.30	1.80m ²
to 2500m	2x	6x	2x	0.30	7.20m ²
	1x	5x	2x	0.30	3.00m ²
	1x	7x	2x	0.35	4.90m ²
	1x	6x	2x	0.30	3.60m ²
	1x	3x	1.50x	0.30	1.350m ²
320	1x	7x	2x	0.30	4.20m ²
370	1x	9x	2x	0.30	5.40m ²
	1x	10x	2x	0.30	6.00m ²
	1x	4x	2x	0.30	6.00m ²
	2x	2x	2x	0.25	2.00m ²
	2x	3x	2x	0.30	3.60m ²
	1x	100x	2x	0.30	3.60m ²

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	1	20	2	0.35	14 m ³
	2	4	2	0.30	4.80 m ³
	1	15	2	0.40	12.00 m ³
	4	4	2	0.30	9.60 m ³
ch 2000 +0	1	3	2	0.30	1.80 m ³
3500 m	1	7	3	0.30	6.30 m ³
	1	8	2	0.30	4.80 m ³
	1	8	2	0.33	5.20 m ³
	1	7	2	0.30	4.20 m ³
	1	15	2	0.30	9.00 m ³
	1	15	2	0.30	9.00 m ³
	1	20	2	0.30	12.00 m ³
	2	7	2	0.30	8.40 m ³
	2	20	2	0.28	22.40 m ³

	1	5	2	0.30	3.00 m ³
	2	7	2	0.30	8.40 m ³
	1	30	2	0.40	4.50 m ³
	1	30	2	0.30	18 m ³
	1	10	2	0.30	6 m ³
	1	30	2	0.30	18 m ³
	2	40	2	0.35	56 m ³
	1	1	2	0.30	0.60 m ³
	1	8	2	0.30	3.00 m ³
	1	30	4	0.25	30 m ³
	1	5	2	0.75	7.5 m ³
	1	5	2	0.30	3 m ³
	1	15	2	0.30	9 m ³
	1	10	2	0.30	6 m ³
	1	100	2	0.35	70 m ³

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	4	2	2	0.30	4.80m ²
	1	50	2	0.30	18m ²
	2	10	2	0.30	12m ²
	1	4	2	0.30	2.40m ²
	1	1.50	12.7	0.30	0.575m ²
	1	4	1.5	0.30	1.80m ²
ch: 38.00	1	2	2	0.35	1.40m ²
5000m ²	1	2.50	1.50	0.25	1.125m ²
	2	4	1.50	0.25	3.468
	2	6	2	0.36	7.20m ²
	1	5	2	0.40	4.00m ²
	3	3	2	0.30	5.40m ²
	1	2	4	0.30	2.40m ²
	2	2	1	0.30	1.20m ²

	3	3	2	0.30	5.40m ²
	4	2	2	0.30	4.80m ²
	1	4	2	0.30	2.40m ²
	1	10	1.75	0.30	5.25m ²
ch: 9400	1	2	1.65	0.25	0.825m ²
6000m ²	1	5	2	0.30	3.00m ²
	2	3	2	0.45	3.00m ²
	1	3	2	0.25	1.50m ²
ch	1	4	2	0.30	2.40m ²
.6800m ²	1	10	1.75	0.30	5.25m ²
7400m ²	1	7	2	0.30	4.20m ²
	1	7	2	0.30	4.20m ²
	1	25	2	0.45	22.50m ²
	1	8	2	0.30	4.80m ²
					<u>667.54m²</u>

A. S. S. S.

02/11/2017

JE

Continuation

