



ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

DETAILED PROJECT REPORT FOR FDR

YEAR-2021-22



BIHAR

Name of the Road :-

Gram Nirpur me Pradhan Mantri Sadak to Nirpur Chowk Tak Via Sahani Tola, Brahman Tola Hote Huye

DISTRICT

Muzaffarpur

DIVISION

Muzaffarpur West

BLOCK

Sahebganj

TOTAL LENGTH OF ROAD

:

2.450

KM

CONSTRUCTION COST

:

3.243

Lac

Submitted By :-
Executive Engineer

RWD Work Division, Muzaffarpur West

3.111

प्रतिवेदन

कार्य का नाम:- Coam Mirpur me pradhanmantri sadak to Khipur chae
tole ka Sahani-tola Barmantola hote hye पथ में अप्रत्याशित बाढ़/अतिवृष्टि से क्षतिग्रस्त पथ में
यातायात चालू करने हेतु आपातकालीन मरम्मत कार्य।

प्रखण्ड-

वित्तीय वर्ष -

प्राक्कलित राशि - Rs. 3.243 lacs
3.111

प्रस्तुत प्राक्कलन जिसकी प्राक्कलित राशि 3.111
3.243 lacs है, प्रखंड- हिलेरा में यातायात बहाली हेतु आपातकालिन मरम्मत के लिए तैयार किया गया है।

अभियंता प्रमुख, ग्रामीण कार्य विभाग, बिहार पटना के पत्रांक 4589 दिनांक 13.11.21 द्वारा दिये गये निर्देश के आलोक में उक्त पथ के क्षतिग्रस्त पथ में Brick Bats & Local Sand भरकर पथ को चालू करने का प्रावधान किया गया है। प्राक्कलन वर्तमान चलू अनुसूचित दर पर तैयार किया गया है। इसकी घटनोत्तर स्वीकृति अपेक्षित है। MIS की प्रविष्टि है। MIS में यह संलग्न है। MIS का SLNO-11

कनीय अभियंता

सहायक अभियंता

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल:-

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- E.E. RWD. Muz. West.

2 Name of Block/Road :- Sahelganj - Gram Nisapur me Panchamantri Sadak to Nisapur
Chauk Tak via Sahni Tola, Brahman Tola, Hote Hye.

(A) For Road:

1. Damage Location/Chainage :-

2. Damage Length :- 12 M.

3. Nature of Damage :- due to flood & heavy rain.

4. Details of Restoration Works :-

(i) Material being used in Restoration works:- Brick Bat - $148.50 m^3$, Sand - $2.10 m^3$

(ii) Equipment's/Tools being used in Restoration works:-

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length :-

This work is found satisfactory.

(B) For Bridge:

1. Damage Location/Chainage :-

2. Damage Length :-

3. Nature of Damage :-

4. Details of Restoration Works :-

(i) Material being used in Restoration works:-

(ii) Equipment's/Tools being used in Restoration works:-

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length :-

NA.

work found satisfactory

Signature of JE/AE/EE

Signature of JE/AE/EE

Signature

(Name of Inspection)

GENERAL ABSTRACT

Name of Road Gram Nirpur me Pradhan Mantri Sadak to Nirpur Chowk Tak Via Sahani Tola, Brahman Tola Hole
 District Huye
 Block Muzaffarpur
 Division Sahebganj
 Length of Road (in Km) Muzaffarpur West

2.450 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	0.000
2	Brick Bats	0.000
3	Sand Filling	3.066
4	Sand bag	0.045
5	H.P.	0.000
	SUB TOTAL	0.000
	GRAND SUB TOTAL	3.243

3.111

3.111

JE Sakb

RWD

AE

RWD

EE

RWD

As Per S.E. RWD (M) Circle Muz
 Letter No 1179 Dated 01/10/2021
 Estimate has been verified by inspecting
 E. E. RWD. (M) Division Mahua

Technically Sanctioned for Rs. 3.111 lac
 (Rs. Three lacs eleven thousand one
 hundred) only (provisionally)

Superintending Engineer
 Rural Works Department
 Work Circle, Muzaffarpur