



ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

DETAILED PROJECT REPORT FOR FDR

YEAR-2021-22



Name of the Road :-		Makari Tola SH-74 to Mushhar Tola Narayan Chowk Tak	
DISTRICT		Muzaffarpur	
DIVISION		Muzaffarpur West	
BLOCK		Sahebganj	
TOTAL LENGTH OF ROAD	:	1.190	KM
CONSTRUCTION COST	:	0.317	Lac

Submitted By :-
Executive Engineer
RWD Work Division, Muzaffarpur West

0.304

प्रतिवेदन

कार्य का नाम:- Makan' - Jolash - 74 to Musahar Jola Naryanchowale
- Jole

..... पथ में अप्रत्याशित बाढ़/अतिवृष्टि से क्षतिग्रस्त पथ में यातायात चालू करने हेतु आपातकालीन मरम्मत कार्य।

प्रखण्ड- Sakhebar

वित्तीय वर्ष -

प्राक्कलित राशि - Rs. 0.319544

0.304

0.304

0.319

प्रस्तुत प्राक्कलन जिसकी प्राक्कलित राशि 516453/- है, PR

..... प्रखण्ड-..... में यातायात बहाली हेतु आपातकालीन मरम्मत के लिए तैयार किया गया है। 516453/-

अभियंता प्रमुख, ग्रामीण कार्य विभाग, बिहार पटना के पत्रांक 4589 दिनांक 13.11.21 द्वारा दिये गये निर्देश के आलोक में उक्त पथ के क्षतिग्रस्त पथ में Brick Bats & Local Sand मरकर पथ को चालू करने का प्रावधान किया गया है। प्राक्कलन वर्तमान चलू अनुसूचित दर पर तैयार किया गया है। इसकी घटनोत्तर स्वीकृति अपेक्षित है। MIS में प्रविष्टि कर दी गई है। MIS में यह हीलान है। MIS का SLNO 10 पर है।

13/11/21
कनीय अभियंता

13/11/21
सहायक अभियंता

13/11/21
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल:-

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- E.E. RWS Pungathapur West

2 Name of Block/Road :- Makani-tola SH-74 Musahani-tola Hazayan chowk
-ta

(A) For Road:

1. Damage Location/Chainage :-
2. Damage Length :- 02 M.
3. Nature of Damage :- due to flood & heavy rain.
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- Brick Bat - 4.4 cum, Sand - 1.2 cum.
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

The work is found satisfactory.

NA

work found satisfactory

Signature of JE/AE/EE

05/11/2021
AE

Signature
13.12.21

(Name of Inspection)

GENERAL ABSTRACT

Name of Road Makari Tola SH-74 to Mushhar Tola Narayan Chowk Tak

District Muzaffarpur

Block Sahebganj

Division Muzaffarpur West

Length of Road (in Km) 1.190 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	0.000
2	Brick Bats	0.237 - 0.310
3	Sand Filling	0.007
4	Sand bag	0.000
5	H.P.	0.000
	SUB TOTAL	0.317
	GRAND SUB TOTAL	0.317

0.304 ✓
0.304

JE 5/11/2021

RWD

AE 5/11/21

RWD

EE 5/11/21

RWD

As Per S.E. RWD (M) Circle Muz
Letter No 1179 Dated 01/10/2021
Estimate has been verified by inspecting
E.E. RWD. (M) Division Muz

Technically Sanctioned for Rs. 0.304 lac
(Rs. Thirty thousand four hundred) only
(provisionally)

28/12/21
Superintending Engineer
Rural Works Department
Work Circle, Muzaffarpur