



ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

DETAILED PROJECT REPORT FOR FDR

YEAR-2021-22



Name of the Road :-	Panchrukhiya Dhala to Tulsi Chowk Hote Huye To Hussepur Siwan Mushari Pull SH Road Tak		
DISTRICT	Muzaffarpur		
DIVISION	Muzaffarpur West		
BLOCK	Sahebganj		
TOTAL LENGTH OF ROAD	:	4.220	KM
CONSTRUCTION COST	:	16.403 15.43622	Lac

Submitted By :-
Executive Engineer
RWD Work Division, Muzaffarpur West

15.436

प्रतिवेदन

कार्य का नाम:- पट्टाखिन्ना दाला - से नुलहा - लोक होल्डिंग्स
एलएन विभाग कुशीनगर-54 पथ में अप्रत्याशित बाढ़/अतिवृष्टि से क्षतिग्रस्त पथ में
यातायात चालू करने हेतु आपातकालीन मरम्मत कार्य।

प्रखण्ड- साहिबगंज
वित्तीय वर्ष - 2021-22
प्राक्कलित राशि - Rs. 12.755 **15.436**

प्रस्तुत प्राक्कलन जिसकी प्राक्कलित राशि 12.755 **15.436** है,
प्रखण्ड- साहिबगंज में यातायात बहाली हेतु आपातकालीन मरम्मत के
लिए तैयार किया गया है।

अभियंता प्रमुख, ग्रामीण कार्य विभाग, बिहार पटना के पत्रांक 4589 दिनांक 13.11.21 द्वारा
दिये गये निर्देश के आलोक में उक्त पथ के क्षतिग्रस्त पथ में Brick Bats & Local Sand भरकर पथ को चालू
करने का प्रावधान किया गया है। प्राक्कलन वर्तमान चलू अनुसूचित दर पर तैयार किया गया है। इसकी
घटनोत्तर स्वीकृति अपेक्षित है। पथ MIS में प्रविष्टि प्र MIS में प्रविष्टि

सिद्धांत
कनीय अभियंता

सिद्धांत
सहायक अभियंता

सिद्धांत
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल:-

Inspection Report for Flood Damage Work

Date:- 2/12/2021

1 Name of PIUs :- E.E.R.W.D, WODH DIVISION Muzir. West.

2 Name of Block/Road :- Sahobganj

(A) For Road:

1. Damage Location/Chainage :-

2. Damage Length :- 80m

3. Nature of Damage :- Road cutting due to

4. Details of Restoration Works :-

(i) Material being used in Restoration works:- Brick & Sand Bag. Brick = 582

(ii) Equipment's/Tools being used in Restoration works:- Road Roller. Sand Bag = 1122

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length :- 80 M

(B) For Bridge:

1. Damage Location/Chainage :-

2. Damage Length :-

3. Nature of Damage :-

4. Details of Restoration Works :-

(i) Material being used in Restoration works:-

(ii) Equipment's/Tools being used in Restoration works:-

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length :-

The work completed found & satisfactory.

T-1-D

work found satisfactory

Signature of JE/AE/EE

Signature of JE/AE/EE

Signature

02-12-21

Signature

(Name of Inspection)

GENERAL ABSTRACT

Name of Road Panchrukhiya Dhala to Tulsu Chowk Hote Huye To Hussepur Siwan Mushari Pull SH Road Tak
District Muzaffarpur
Block Sahebganj
Division Muzaffarpur West
Length of Road (in Km) 4.220 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	0.000
2	Brick Bats	10.938 12.091
3	Sand Filling	0.000
4	Sand bag	4.438 4.312
5	H.P.	0.000
	SUB TOTAL	16.403
	GRAND SUB TOTAL	16.403


15,43,627 =
15.436


JE

RWD


AE


RWD


EE

RWD

As Per S.E. RWD (M) Circle Muz
Letter No. 1179 Dated 01/10/2021
Estimate has been verified by inspecting
E.E. RWD. (M) Division

Technically Sanctioned for Rs. 15.436 lacs
(Rs. Fifteen lacs forty three thousand six
hundred) only (provisionally)


28.2.22
Superintending Engineer
Rural Works Department
Work Circle, Muzaffarpur