

Inspection Report for Flood Damage work

Date:-

1 Name of PIUS :-

Modhepura

2 Name of Block :-

Murhganj

3 Name of Road :-

Rajghathpur ward no-7 MC P.M.C.S.Y Road se Durga sthan tk

A. For Road

1 Damage Location/Chainage :- 0 to 60m, 60 to 105m, 105 to 125m, 125m to 155, 155 to 220, 220 to 525

2 Damage Length :- 0.216 km

3 Nature of damage :-

4 Details of Restoration Works :-

i Material being used in Restoration works:-

Bridle bats, local sand, cement bags, bamboo

ii Equipments/Tools being used in Restoration works :-

iii Procedure taken up in Restoration works :-

iv Restored Length :-

B. For Bridge

1 Damage Location/Chainage :-

2 Damage Length :-

3 Nature of damage :-

4 Details of Restoration Works :-

i Material being used in Restoration works:-

ii Equipments/Tools being used in Restoration works :-

iii Procedure taken up in Restoration works :-

iv Restored Length :-

A. K. Sanyal
JE

Prakash
01/11/21
AE

01/11/21
EE

Signature
(Name of inspector)

Schedule XLV-Form No. 134

Madhepura

DIVISION

Myrshiras

SUB-DIVISION

Ra. Gunahpur Ward no 7 Me. Phasur Road Se. Durgashan
Jyoti

Measurement Book

Name to work— 1
 Situation of work—
 Agency by which work is executed—
 Date of measurement—
 No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work—	Rajunapur				
Ward no.—	The P.M.C.S.Y Roadie				
	durga Ashan etc.				
Agency—	Ranjay Yachan				
	Final Final A/c bill				
Item—(1)	providing and laying				
	Ricks bet				
Ch 08 60	1	24.35	3.65	0.25	22.8

	1	26.85	4.05	1.52	165.28
60 to 105	1	11.89	2.43	0.15	4.33
105 to 125	1	9.00	2.43	0.125	3.82
125 to 155	1	12	4.30	2.20	113.52
	1	13	3.65	2.15	102.01
155 to 220	1	30	2.43	0.25	18.22
	1	12	0.60	0.45	3.24
	2	22	0.60	0.45	11.88
220 to 525	1	21.64	3.65	2.10	165.87
	1	3	2.43	0.15	1.09
	2	9	0.60	0.20	2.16
	1	21	4.00	0.15	12.60
					626.31 H
Item 2	Sand Filling in				
	for road				
	1	30	3.65	0.075	8.21

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	1x	29	3.65	0.075	7.93
	1x	26.85	4.05	0.075	8.15
	1x	11.89	2.43	0.075	2.11
	1x	12	4.27	0.075	3.83
					30.30

<u>Item-5</u>	Labour for cutting				
	62mm 75mm dia bamboo				
	Piles				
	1x	95	2.13	=	202.35
	1x	51	2.13	=	108.63
					310.98

<u>Item-4</u>	Labour for fixing				
	and fixing bamboo				
	Chuchin				

	1x	21.64	2	=	43.28
	1x	25	2	=	50.00
					93.28
					396.09

<u>Item-5</u>	Labour for fixing				
	and fixing 75mm				
	dia bamboo 4mm				
	3x	25	=	75.00	
	3x	21.64	=	64.92	
					139.92

<u>Item-1</u>	Supply of bamboo				
	at site - 846.99				
			=	141.10	

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	item no (3)	—	310.98m		
	Q	45.86/m	—		14262.00
(4/4)	Labour for filling and filling bamboo chachri				
	V.T.M.B.P.No-(2)				
	item no (4)	—	93.28m		
	Q	78.20/m	—		7294.00
(5/5)	Labour for filling and filling 75mm dia bamboo tubes				
	V.T.M.B.P.No-(2)				
	item no (5)	—	139.92m		
	Q	5.21/m	—		742.00

(6/6)	Supply of Bamboo of size				
	V.T.M.B.P.No-(2)				
	item no (6)	—	141 m		
	Q	188.39/m	—		26563.00

(7/7)	Labour for filling empty cement beds with local sand				
	V.T.M.B.P.No-(3)				
	item no (7)	—	1015 m		
	Q	37.05/m	—		37609.00
					1308448.00

Continuation

