

Inspection Report for Flood Damage work

Date:-

1 Name of PIUS :-

Madhepura

2 Name of Block :-

Murhiganj

3 Name of Road :-

Rathanpatti more se Mahhara P.M.G.S.Y kharar

A. For Road

1 Damage Location/Chainage :-

0+83m 83 to 280, 280 to 395, 395 to 525, 525 to 625, 625 to 720m

2 Damage Length :-

0.541 km

3 Nature of damage :-

4 Details of Restoration Works :-

i Material being used in Restoration works:-

Bricks bats, Local sand

ii Equipments/Tools being used in Restoration works :-

iii Procedure taken up in Restoration works :-

iv Restored Length :-

B. For Bridge

1 Damage Location/Chainage :-

2 Damage Length :-

3 Nature of damage :-


4 Details of Restoration Works :-

i Material being used in Restoration works:-


ii Equipments/Tools being used in Restoration works :-

iii Procedure taken up in Restoration works :-

iv Restored Length :-




JE



AE



EE



Signature

(Name of inspector)

Schedule XLV-Form No. 134

Maddhepura

DIVISION

Muxhigans

SUB-DIVISION

Rajharpatti more se machhara PMGSI nahar

Measurement Book

Name for work—

1

Situation of work—

Agency by which work is executed—

Date of measurement—

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work—	Rathnan Patti				
	more se mahhara PMSS				
	Nohar				
Agency—	Rani Kumari				
	Est and Final A/C Bill				
Item—(1)	providing and laying				
	of Bricks bat				
Ch 08083	1x	19.81x	2.74x	0.450	24.42
	1x	3.00x	2.30x	0.300	2.070

	1x	29x	1.50x	0.225	9.78
830280	1x	13x	1.50x	0.225	4.38
	1x	5.00x	2.75x	0.300	4.12
	1x	5.00x	1.25x	0.300	1.87
	1x	16.00x	3.30x	0.280	13.20
	1x	6x	2.50x	0.300	4.50
	1x	2x	2.50x	0.300	1.50
	1x	30x	3.40x	0.200	20.40
2800395	1x	10x	3.40x	0.250	8.50
	3x	30x	3.40x	0.250	76.50
3950525	3x	30x	3.40x	0.200	91.80
	1x	30x	3.40x	0.250	25.50
5250625	3x	30x	3.40x	0.250	76.50
	1x	10x	3.40x	0.225	7.65
6250720	1x	3x	2.43x	0.150	1.09
	1x	29x	3.30x	0.300	28.71

Continuation

