

# INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 06.06.2022		District: Aurangabad
Division : Aurangabad		Length (km): 5.906 KM
Name of the Road: Dew to Kauchanpur path		
Scheme/Programme:		MR-3054

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	V
b)	Riding Quality	V
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
e)	Contraction Joints provided or not (CC Pavement)	—
f)	Compaction of flank/slope & raincuts if any	S
<b>Observation Remarks:-</b> Some potholes found at different locations		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S
<b>Observation Remarks:-</b>		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
<b>Observation Remarks:-</b>		
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :


Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:-

Designature:-

Pramod Kumar  
EE, Reg. Lab, Sasaram

  
06/06/22 (Signature)

6/6/22