

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 06.06.2022	District: Aurangabad
Division : Aurangabad	Length (km): 0.500 KM
Name of the Road: Devkanchaypur Road to Mahuadohar	
Scheme/Programme:	MMGSY

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	U
e)	Contraction Joints provided or not (CC Pavement)	U
f)	Compaction of flank/slope & raincuts if any	S

Observation Remarks:-
 (i) Some small visible cracks found
 (ii) Joint not properly provided

2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	S
d)	Condition of Vent Clearance	S

Observation Remarks:-

3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S

Observation Remarks:-

4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:-
 Designature:-

Pramod Kumar
 EE, Reg. Lab, Sagar

(Signature)
 06/06/22
 AE

6-6-22