

# INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 9.6.22		District: Aurangabad
Division : Aurangabad		Length (km): 0.950 km
Name of the Road: Sekh Bighya to Amba Daltengang Road		
Scheme/Programme:		MMGSY (SC)
Sl. No.	Parameters to be checked	Remarks (S/U)
<b>1.</b>	<b>Pavement</b>	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
e)	Contraction Joints provided or not (CC Pavement)	—
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:-		
<b>2.</b>	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S
Observation Remarks:-		
<b>3.</b>	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:-		
<b>4.</b>	<b>Compliance History</b>	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Satisfactory

Name of Officer:-  
Designature:-

Pranod Kumar  
FE, Reg. Lab, Sagar  
Rup

(Signature)  
9/6/22