

INSPECTION REPORT FOR ONGOING ROADS		
Name of Road: <u>T64 Jogari to Barde</u>		
District: <u>Aurangabad</u>	Division: <u>Aurangabad</u>	Block: <u>Madaupur</u>
Length of Scheme (in km): <u>1.560 KM</u>		Name of Scheme/Programme:
Status of Project:	Ongoing <u>MMGSY (SC)</u>	
Sr. No.	Parameters to be Checked for Construction work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing under Construction	S
Description of observation :		
b)	Adequate Thickness of pavement layers constructed (Sub-base/ Base Course/ Wearing Course/ CC Pavement)	S
Description of observation :		
c)	Quality of Construction Material Used	S
Description of observation :		
d)	Whether free from any defects and Irregularity example- Undulation, Poor Compaction, Poor Gradation, exposed aggregates in case of CC Pavement, Surface Cracks, Poor workmanship, etc.	S
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	S
Description of observation :		
2	Cross Drainage Structure	S
Description of observation of CD works :		
Remark if any:		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	<u>Satisfactory</u>
---------------------------------------	---------------------

Name of Officer: Pranod Kumar

Designation: EE, Reg. Lab. Sarason
RWD

07/06/22 (Signature)
AE