

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection :	04.06.2022	District:	Aurangabad
Division :	Aurangabad	Length (km):	3.600KM
Name of the Road:	Amba Jeeva bigha road to Kasauti		
Scheme/Programme:	New M.R.		
Sl. No.	Parameters to be checked	Remarks (S/U)	
1.	Pavement		
a)	Condition of Surfacing	S	
b)	Riding Quality	S	
c)	Road Camber	S	
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—	
e)	Contraction Joints provided or not (CC Pavement)	—	
f)	Compaction of flank/slope & raincuts if any	S	
Observation Remarks:-			
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting.	S	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S	
c)	Condition of railings/slab/approach for Bridges	—	
d)	Condition of Vent Clearance	S	
Observation Remarks:-			
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S	
Observation Remarks:-			
4.	Compliance History		
a)	Status of ATR's & any others	—	

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

Satisfactory

Name of Officer:-
Designature:-

Pranod Kumar
EE, R-1ab Sasaram

04/06/22
(Signature)