

INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection : 06.06.2022		District: Aurangabad
Division : Aurangabad		Length (km): 2.460 KM
Name of the Road: Dev More to Uperdaha		
Scheme/Programme: New MR		

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	U
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
e)	Contraction Joints provided or not (CC Pavement)	—
f)	Compaction of flank/slope & raincuts if any	S
Observation Remarks:- 4) Some small potholes found in between CH 1800 to CH 2000 m. Maintenance work was going on during the time of inspection.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
d)	Condition of Vent Clearance	S
Observation Remarks:-		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S
Observation Remarks:-		
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

U

Name of Officer:-

Designature:-

Pramod Kumar

EE, Reg. Lab, Sasuram


 06/06/22 (Signature)