## INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection: 9.6.22			District: Aurengaberd		
Division: Aurangabad			Length (km): 3.700 LOY		
	the Road: Bay	Kan . Badohi	Rly str. to Tai stee Big! New maintenance Pol	ha via Mirzabu	
Scheme	icy)				
Sl. No.	P 4 2 4 4 5 4 6 6 7 6 7 6 7 6 7 6 7 6 7 6 7 6 7 6 7	Parameters to l	oe checked	Remarks (S/U)	
1.	Pavement			of A of	
a)	Condition of Surfacing			S	
b)	Riding Quality				
c)	Road Camber	S			
d)	Whether free aggregates in c	<b>-</b> .			
e)	Contraction Joints provided or not (CC Pavement)			_	
f)	Compaction of flank/slope & raincuts if any			5	
Observ	ation Remarks:-	•			
	To the second se				
2.	Cross Drainag	A State of the sta	leader in alleding its pointing	S	
a)	Condition of head walls in Hume pipe culverts including its painting  Condition of Abutment & Wing walls, Slab in RCC culverts				
b)					
c)	Condition of railings/slab/approach for Bridges				
d)	Condition of Vent Clearance				
Observ	atton Remarks	** September 18 September 19 Sep			
3.	Road Furnitur	<b>e</b>			
а)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained				
Observa	ation Remarks:-			,	
4.	Compliance Hi	story		E. C. M. C. C.	
a)	Status of ATR's	& any others			

Overall Rating :	Satisfactory (S)/ Unsatisfactor	ry (U)	satistactory
Name of Officer:- Pray Designature:- 1212, Rub		S Ob 12 Signat	101 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1