## INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection: 07.06.2022 District: Aurangaban				
Division: Aurangaba Length (km): 41050 KM				
Name of the Road: G. t. Road to Shailway Mahuarwa				
Scheme	/Programme: New MR	Ď amarika (S/II)		
Sl. No.	Parameters to be checked	Remarks (S/U)		
1.	Pavement			
a)	Condition of Surfacing	5		
b)	Riding Quality	S		
c)	Road Camber	S		
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	<del>-</del>		
e) '	Contraction Joints provided or not (CC Pavement)	<u>-</u>		
f)	Compaction of flank/slope & raincuts if any	S		
Observation Remarks:-				
		. :		
	•			
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	S		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			
c)	Condition of railings/slab/approach for Bridges			
d)	Condition of Vent Clearance	S		
Observation Remarks:-				
		<i>A</i>		
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S		
Observat	ion Remarks:-			
4.	Compliance History			
a) :	Status of ATR's & any others	. —		
	lating			
Overall Rating : Scaling Scaling Scaling				

Overall Rating	Satisfactory (S)/ Unsatisfac	ctory (U)	Scalinfactory
	Pramod leuon ar	ON Ob My (Signa	ture) 7/6/22