## INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection: 8.6.22				District: Aurangabad				
Division	1: Aurangal	bad	Lengt	h (km):	2.500			
Name o	of the Road: Au	rangahad	Nabinago	as social		2at pur	, , , , , , , , , , , , , , , , , , ,	
Scheme/Programme: MR-3054 (New maintenance Pol				F02049	emarks (S/U)			
Sl. No.		Parameter	s to be check	ked	1.75 to 1.15 to 1.	**************************************	emates (670)	
1.	Pavement							
a)	Condition of Surfacing				<u>S</u>			
b)	Riding Quality				<u>.</u> _S			
c)	Road Camber						S	
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				sed			
e) .	Contraction Joi	ints provided or 1	not (CC Pave	ment)				
f)		flank/slope & ra			77	2. 1	<u> </u>	
	vation Remarks:-							
						s startised caste	nese se estados estados estados estados en e	
			Country and white speek it is	San Carlo	onskie (* 1865) Onskie (* 1865)		Táire de la comhlaíon	
2.	Cross Draina					.	Sh	
<b>2.</b> a)	Condition of he	ead walls in Hun				ing	<u>S</u>	
	Condition of A	ead walls in Hun butment & Wing	g walls, Slab	in RCC culv		ing	S.	
a)	Condition of A	ead walls in Hun	g walls, Slab	in RCC culv		ing	<u>s</u>	
a) b) c) d)	Condition of A Condition of ra Condition of V	ead walls in Hun butment & Wing ailings/slab/appro ent Clearance	g walls, Slab	in RCC culv		ing		
a) b) c) d)	Condition of A Condition of ra	ead walls in Hun butment & Wing ailings/slab/appro ent Clearance	g walls, Slab	in RCC culv		ing	<u>s</u>	
a) b) c) d)	Condition of A Condition of ra Condition of V	ead walls in Hun butment & Wing ailings/slab/appro ent Clearance	g walls, Slab	in RCC culv		ing	<u>s</u>	
a) b) c) d)	Condition of he Condition of A Condition of ra Condition of V vation Remarks:-	ead walls in Hundbutment & Wing hillings/slab/appro ent Clearance	g walls, Slab	in RCC culv	verts		<u>s</u>	
a) b) c) d)	Condition of he Condition of A Condition of ra Condition of V vation Remarks:  Road Furnitus Whether sign	ead walls in Hun butment & Wing ailings/slab/appro ent Clearance	g walls, Slab	in RCC culv ges	verts		<u>s</u>	
a) b) c) d) Observ	Condition of he Condition of A Condition of ra Condition of V vation Remarks:  Road Furnitus Whether sign	re boards/informatent road markings	g walls, Slab	in RCC culv ges	verts		<u>s</u>	
a) b) c) d) Observ	Condition of he Condition of A Condition of Y Condition of V Vation Remarks:-	re boards/informatent road markings	g walls, Slab	in RCC culv ges	verts		<u>s</u>	
a) b) c) d) Observ	Condition of he Condition of A Condition of Y Condition of V Vation Remarks:-	re boards/informatent road markings	g walls, Slab	in RCC culv ges	verts		<u>s</u>	

Overall Rating	: Satisfactory (S)/ Unsatisfac	ctory (U) Scalinged by
Name of Officer:- Designature:-	Proposed Lumen EE, Reg. Lab, Sasaran Rho	(Signature) \$\frac{100}{8/6/22}