## INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date of Inspection: 7.6.22 District: Auranzo-bad				
Division: Aurangabad Length (km): 3.00 km				
Name of the Road: 60-144-To4 to Bhuya bigha tak				
Scheme/Programme: PMGSY				
SI. No.	Parameters to be checked			Remarks (S/U)
451.	Pavement			
a)	Condition of Surfacing			S
b)	Riding Quality			S
c)	Road Camber			S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			S
c)	Contraction Joints provided or not (CC Pavement)			S
f)	Compaction of flank/slope & raincuts if any			5
Observation Remarks:-				
2				* * * * * ·
		rage y		· · ·
2	Cross Drainage		artegralisas, plant	Something of the second
a)	Condition of head walls in Hume pipe culverts including its painting			S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S
c)	Condition of railings/slab/approach for Bridges			·
d)	Condition of Vent Clearance			S
Observation Remarks:-				
	and the second s	trus and		AND THE POST OF THE PARTY OF
3,	Road Furniture			
a)	Whether sign boards/informatory/cautiona stones/Pavement road markings are provide	ry Board/ d and main	km & 200m ntained	S
Observation Remarks:-				
	25%.0.3			
4.	Compliance History			
a)	Status of ATR's & any others			
Overall Rating : [ C 0: A 1				
Ovciali	IMMILIE.		X # TO	- A1 /) A

Name of Officer:- Pragnod Luranay
Designature:- EE, Reg. Lab. Sasaran
Rup

(Signature)

(Signature)