



ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

DETAILED PROJECT REPORT FOR FDR



Name of the Road :-		Kotwara Chowk PMGSY Road to Dakshin Mohammadpur Village Tak	
DISTRICT		Muzaffarpur	
DIVISION		Muzaffarpur West	
BLOCK		Paroo	
TOTAL LENGTH OF ROAD		:	0.300 KM
CONSTRUCTION COST		:	9.373 9.774 Lac

Submitted By :-
Executive Engineer
RWD Work Division, Muzaffarpur West

प्रतिवेदन

कार्य का नाम:- Kotwar Chowk pmsy road to Mahan

Mohamonal pmsy village पथ में अप्रत्याशित बाढ़/अतिवृष्टि से क्षतिग्रस्त पथ में यातायात चालू करने हेतु आपातकालीन मरम्मत कार्य।

प्रखण्ड- Parrot

वित्तीय वर्ष - 2021-22

प्राक्कलित राशि - Rs. 9.379 lacs

प्रस्तुत प्राक्कलन जिसकी प्राक्कलित राशि 9.379 lacs है, प्रखण्ड- Parrot में यातायात बहाली हेतु आपातकालीन मरम्मत के लिए तैयार किया गया है।

अभियंता प्रमुख, ग्रामीण कार्य विभाग, बिहार पटना के पत्रांक 4589 दिनांक 13.11.2021 द्वारा दिये गये निर्देश के आलोक में उक्त पथ के क्षतिग्रस्त पथ में Brick Bats & Local Sand भरकर पथ को चालू करने का प्रावधान किया गया है। प्राक्कलन वर्तमान चलू अनुसूचित दर पर तैयार किया गया है। इसकी घटनोत्तर स्वीकृति अपेक्षित है। पन्नों की प्रतिलिपि प्रमाणित है, प्रति संलग्न है।

8/11/2021
कनीय अभियंता

8/11/2021
सहायक अभियंता

11/11/2021
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल:-

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- EE Rwd. women's div muz west

2 Name of Block/Road :- paroo / Kothara chok gramy road to Dakshin
mohammadpur village taluk

(A) For Road:

1. Damage Location/Chainage :- 0.6 km
2. Damage Length :- 18 m
3. Nature of Damage :- Road damage by Flood & Heavy rain
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- Bricks natz - 448.33 m, sand - 24600 m³
 - (ii) Equipment's/Tools being used in Restoration works:- Roller, Tipper
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 18 m

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

The work found satisfactory

N/A

The work is found satisfactory

Signature of JE/AE/EE
13/11/2021

Signature
02.12.21

(Name of Inspection)

Road Kotwara Chowk PMGSY Road to Dakshin Mohammadpur Village Tak

et Muzaffarpur

ck Paroo

Division Muzaffarpur West

0.300 Km

Length of Road (in Km)

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	0.000
2	Brick Bats	9.256 -9.655
3	Sand Filling	0.123 0.120
4	Sand bag	0.000
5	H.P.	0.000
	SUB TOTAL	7.379 9.774
	GRAND SUB TOTAL	9.379 -9.774
		9.38,854

JE 15/11/2021

RWD

AE 15/11/2021


RWD

EE 15/11/21

RWD

As Per S.E. RWD (W) Circle Muz.
Letter No 1179 Dated 01/6/2021
Ess note has been verified by inspecting
E.E. RWD. (W) Division

Technically Sanctioned for Rs. 9.379 lacs
(Rs. Nine lacs thirty seven thousand
nine hundred) only (provisionally)


26.12.21
Superintending Engineer
Rural Works Department,
Work Circle, Muzaffarpur.


27.12.21