

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Andherthari

Name of Road :- Repair of road from Pipraight to Fulparas.

A. For Road

1. Damage Location Chainage :- 4.90 km, 7.00 km and 8.10 km change.
2. Damage Length :- 200.3 mtr
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:- Brick Bats
 - ii. Equipment's/Tools being used in Restoration works:- Tractor, J.C.B
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:- 200.3 m

B. For Bridge

1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

N/A

C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-

Signature of JE/AE/EE

20/4/20
ER

Signature
(Name of Inspection)

W/R:- Repair of Road from Pipraghat to
Fulpara (Notable done) FDR
Shedule XLV Form No. 134.

R.W.D. Thangbarpur

DIVISION

Andhra Pradesh

SUB-DIVISION

3132

Measurement Book

Name of Work-

Situation of Work-

Agency by which work is executed-

Date of Measurement-

No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
M/W:- Restoration of Embankment - shoulder with Border but in Repair Road from Pibraghat to Fulpasag.					

Agency:- Departmental work.					
Authority:- E. E. R. W. D					
Jhangharan					
Block - Andhra Pradesh					
Measurement as per T.S.					
① Restoration of drain cut with border but in shoulder & Embankment					

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1x44.00x4.00x0.30 =					52.80 m ³
1x4.50x1.30x0.15 =					0.88
1x10.00x3.40x0.30 =					10.20
1x43.00x4.00x0.30 =					51.60
1x24.80x4.00x0.30 =					29.76
1x5.00x2.80x0.15 =					2.10
1x24.00x3.60x0.30 =					25.92
1x45.00x4.00x0.30 =					54.00
					227.26
					m ³
(Signature)					
22/6/22					

Abstract of cost

① Asst. & Pullup brick
bed in Embank
& shoulder

227.26 m³ at 2004 =

CA 2004 = 26/1431 455647-

455647-

Add 12% GST 54677=

1% L. 455620

At 2015. Fees 10% PM. 64.

227.26 m³ Continuation

CS 1032/m

4/11 23453=

5383342

[illegible]