

कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, जमुई।

पत्रांक ४७२/२०२०

जमुई, दिनांक 18.6.2022

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, जमुई।

सेवा में,

नोडल पदाधिकारी,
3054(MR)
ग्रामीण कार्य विभाग,
बिहार, पटना।

विषय:—

शीर्ष MR New Maintenance Policy 2018 योजना अन्तर्गत 5(पाँच) वर्षीय अनुरक्षण का
आवंटन उपलब्ध कराने के संबंध में।


महाशय,

उपर्युक्त विषयक के संबंध में कहना है कि शीर्ष MR New Maintenance Policy 2018
योजना अन्तर्गत 5(पाँच) वर्षीय अनुरक्षण के पथों का पथवार मांगी जाने वाली आवंटन की सूची पत्र के
साथ भवदीय के अवलोकनार्थ एवं आवश्यक कार्रवाई हेतु समर्पित की जा रही है।

सूचनार्थ सादर समर्पित।

अनु०— यथोक्त

विश्वासभाजन



कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमण्डल, जमुई।

STANDARD FORMAT FOR ROADS QUARTERLY STATEMENT

PIU Name :- RWD(WD), Jamui			
Block Name:- Jamui			
1	Name of the Road	Garsanda - Sonpe Bukar via Baladih (Missing Link)	
2	Batch No.	RM/JA/JAM/19/0012	
3	Project ID	20804102025	
4	Total Lenth of Road (in KM)	2.0	
5	Length of Road to Meet Required Service Level [Completed length](in Km) [1]	2.0	
6	No. of Total Quarter (ie 3 Months as a unit) in 5 years	20	
7	Ordinary Maintenance Cost as per Schedule [Agreement Amount for Maintenance] (in Lakh)	18.73264	
8	Quarterly Payment : 1/20 of Ordinary Maintenance Cost as per Schedule (in Lakh) [2]	0.93663	
Compliance Criteria	Standard Job Description	Non-Compliance	Reduction Payment [6]=[3]/[1]*[2]*[4]
		Length Non- Compliant [3]	Weighted Value for Payment Reduction (%) [4]
I	PAVED ROADS (CARRIAGEWAY)	0	60%
II	SHOULDERS AND EMBANMENTS	0	10%
III	CROSS DRAINAGE INCLUDING CULVERTS AND BRIDGES	0	15%
IV	SIGNAGE AND ROAD SAFETY	0	10%
V	VEGETATION	0	5%
TOTAL PAYMENT REDUCTION FOR THE QUARTER (IN Lakh) [5]			0.00000
TO BE PAID FOR THE QUARTER/DEMAND (in Lakh) [6]			0.93663

Date of inspection by E/I or his agent
Prepare by Contractor's self Control unit

Name and Designation of person inspecting road

Date

(Signature)



Signature of person inspecting road

Certify by E/I [signature] Date:-
Executive Engineer
Rural Works Department
Works Division, Jamui

SUMMARY OF ORDINARY MAINTENANCE INSPECTION REPORT

Road From: Santanda some Bihar via Bhabhi (missing link)

(Package No. AM/11/AM/19/0012)

Length of Road :- 2.05Km

Inspector :- J.E. Ward Sub Division Jambul

To:-

Executive Engineer
R.W.D, Works Division Jambul

Date: 17.6.2022

Position :- J.E

No	Standard Of Work Item Name	Work Unit	Unit Of Required in each Kilometer										Comments
			1	2	3	4	5	6	7	8	9	10	
OM190	Sealed pavement												Comments
OM191	Asphalt Patching	m ²	Nil	Nil	Nil	Nil							No Nil Hole Found
OM192	Surface Depression and Rut patching	m ³	Nil	Nil	Nil	Nil							Not Surface Depression & Rut Patching Found
OM193	Crack Sealing	Ln	Nil	Nil	Nil	Nil							No Crack sealing Found
OM194	Surface Treatment												
	(a) Loss of Aggregate (Surface Raveling)	m ²	Nil	Nil	Nil	Nil							No Loss Of Aggregate (Surface Raveling) Found
	(b) Bleeding / Flushing	m ²	Nil	Nil	Nil	Nil							No Bleeding/ Flushing Required
	(c) Corroble Cracking	m ²	Nil	Nil	Nil	Nil							No Corroble Cracking Found
195	Edge Repair	m ²	Nil	Nil	Nil	Nil							No Edge Repair Required
196	Deposits	m ²	N.A	N.A	N.A	N.A							
197	Concrete pavement	m ³	N.A	N.A	N.A	N.A							
	Other activities												
OM200	Shoulder												
	Unsealed Shoulder												
OM201	(a) Edge Drop-off	Ln	Nil	Nil	Nil	Nil							No Edge Drop Off Required
	(b) Roughness, Scouring or Potholes	Ln	Nil	Nil	Nil	Nil							Not Required
	(c) Standing water	Ln	Nil	Nil	Nil	Nil							No Standing Water Found
OM202	Embankment Repair	m ³	Nil	Nil	Nil	Nil							Not Required
	Other activities (Lean Cure)												Not Required
OM203	Overage including culverts major												
OM204	Surface Drains & Verge	Ln	N.A	N.A	N.A	N.A							Not Required
OM205	Surface Drains & Verge	Ln	N.A	N.A	N.A	N.A							Not Required
OM206	Surface Cleaning	m ²	Nil	Nil	Nil	Nil							Not Required
OM207	Culvert and pit Repair	m ²	Nil	Nil	Nil	Nil							Not Required
OM208	Other activities(White washing)	m ²	Nil	Nil	Nil	Nil							Not Required

No	standard Of Work Item	Work	Unit Of Required in each Kilometer										Comments
			1	2	3	4	5	6	7	8	9	10	
OM400	Vegetation												
	Grass Control												
	(a) Roadside-General Tidy	Ha	Nil	Nil	Nil	Nil							Not Required
OM401	(b) Clear near Safety signs, kilometer posts and roadside furniture	Ha	Nil	Nil	Nil	Nil							Not Required
	Tree and Shrub Management	No	Nil	Nil	Nil	Nil							Not Required
OM402	Cutting Of Branches Of Trees	No	Nil	Nil	Nil	Nil							Not Required
	Cutting Of Shrubs From Road Way	No	Nil	Nil	Nil	Nil							Not Required
	Other activities (Trimming of Grass)	M ²	Nil	Nil	Nil	Nil							Not Required
OM500	Safety Signage and Road		Nil										Not Required
OM501	Signs Maintenance	No	Nil	Nil	Nil	Nil							Not Required
OM502	Guard Stones	Lm	N/A	N/A	N/A	N/A							Not Required
OM503	Distance Stones	No	N/A	N/A	N/A	N/A							Not Required
OM504	Road Marking	M ²	Nil	Nil	Nil	Nil							Not Required
	Other activities												

Bidder

Executive Engineer, R.W.D.Works Division-Jamui

Division,Jamui

unlabeled

Name of Work-Gairsanda - Sonpe Bukar via Baladth (Missing Link)

Name of Contractor-Jitendra Kumar Singh

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event
28/5/22	16:8:3	39	0.1	350	0	3500	3239	G	24.90989	86.253265	Normal
28/5/22	16:8:38	39	0.1	340	10.1	3400	3156	G	24.91077	86.25348	Normal
28/5/22	16:9:15	39	0.1	330	10.1	3300	3073	G	24.91169	86.253687	Normal
28/5/22	16:9:15	39	0.1	300	10.1	3000	2825	G	24.9126	86.253888	Normal
28/5/22	16:10:0	39	0.1	150	10.1	1500	1583	G	24.91344	86.254107	Culvert
28/5/22	16:10:0	39	0.1	250	10.1	2500	2411	G	24.91425	86.254308	Curve
28/5/22	16:10:25	39	0.1	350	10.1	3500	3239	G	24.915	86.254427	Normal
28/5/22	16:11:0	39	0.1	390	10.1	3900	3570	G	24.91562	86.254123	Speed Breaker
28/5/22	16:11:0	39	0.1	350	20.2	3500	3239	G	24.91647	86.254477	Normal
28/5/22	16:11:0	39	0.1	320	30.3	3200	2991	G	24.91739	86.254813	Normal
28/5/22	16:11:35	39	0.1	300	10.1	3000	2825	G	24.9175	86.255522	Normal
28/5/22	16:12:0	39	0.1	320	30.3	3200	2991	G	24.9172	86.256515	Normal
28/5/22	16:12:11	39	0.1	370	30.3	3700	3405	G	24.91707	86.257473	Speed Breaker
28/5/22	16:12:11	39	0.1	310	30.3	3100	2908	G	24.91698	86.258502	Normal
28/5/22	16:12:11	39	0.1	320	30.3	3200	2991	G	24.9166	86.259377	Normal
28/5/22	16:12:46	39	0.1	250	40.4	2500	2411	G	24.91618	86.260318	Normal
28/5/22	16:12:46	39	0.1	240	40.4	2400	2328	G	24.91578	86.261245	Normal
28/5/22	16:13:0	39	0.1	270	40.4	2700	2577	G	24.91549	86.262087	Normal
28/5/22	16:13:0	39	0.1	270	40.4	2700	2577	G	24.91524	86.263063	Culvert
28/5/22	16:13:21	39	0.1	350	10.1	3500	3239	G	24.91504	86.26414	Normal
		Length	2			Total IRI	57578				
						Average IRI	2878.9				

$$Y = 0 * X^2 + 0.828 * X + 341.6$$

$$X = 3500$$

$$Y = 3239$$

(R) RURAL ROAD

Good Average Poor
<4000 4001-5000 >5001

19/5/22

Executive Engineer

Rural Work Department

Works Division-Jamui

6 Analyzer

Name of Customer :	Jiendra Kumar Singh
Name of Work/ Road :	Garsanda - Sonpe Bukar via Baladith
Lab Job number :	
Date :	28-05-2022
Section No. :	39

Test Date :	28-05-2022	Road Name :	Garsanda - Sonpe Bukar via Baladith
Machine No. :	399	Road Type :	(R) RURAL ROAD
Start S. No. :	0.000	Side :	
Start E. No. :	2.000	Interval :	
Weather :		UV Range :	583 To 5000 1000 mm/km
Start Location :		Dist Range :	0 To 2.1 0.1 -1000 m
End Location :		Equation :	$Y = 0 \cdot X^2 + 0.828 \cdot X + 341.6$

Print Generate Report and Graph

Redraw Graph

Map View

File : D:\RTTM\my policy offline Raquion\Ashok\Jiendra\Sonpey\28081613\Xs, Section No.: 39, Eqn: $Y = 0 \cdot X^2$

Name of Customer : Jiendra Kumar Singh, Name of Work/ Road : Garsanda - Sonpe Bukar via Baladith (Missing)

