

FID/R-2021-2022

Schedule XLV-Form No. 134

Repair of Road from Machhepaly
to Phesga Na Bhitla Bheg men Aor

~~Executive Engineer~~

~~Rural Works Department~~

~~Works Division, Jirangharpur~~

DIVISION

Machhepaly

SUB-DIVISION

3134

MEASUREMENT BOOK

30

1

Name of work—

Situation of work—

Agency by which work is executed—

Date of measurement—

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
F.D.R					
Name of work: Motorability					
of Road Damaged					
By Flood from Repair					
of Road from Madhe					
Pur to Bhajga via					
Bhitha Bhageran Pur					
For year-2021.					
Name of Agency: Department					
of					

Block - Madhe pur
 Authority: Ret. Sdys R.W.D.
 (Mang) Jhanghar Pur

Record Measurement
 1. Provisional and filly
 bricks bats in a ditch.
 Damaged embankment
 including cost of Bricks
 bats and labour all
 complete 50 bps per
 specification and kind 1
 C.V.
 P.T.D.

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2 KM to 6 KM					
1 x 13.0 x 1.70 x 0.30			1.70	0.30	6.63 m ³
1 x 5.50 x 2.30 x 0.50				0.50	6.33 m ³
2 x 8.50 x 1.50 x 0.30				0.30	7.65 m ³
3 x 4.50 x 1.60 x 0.40				0.40	8.64 m ³
1 x 3.0 x 2.30 x 1.0				1.0	6.90 m ³
1 x 3.0 x 2.0 x 0.45				0.45	2.70 m ³
6.01 KM					
1 x 16.0 x 1.50 x 0.30				0.30	7.20 m ³
2 x 10.0 x 1.10 x 0.40				0.40	8.80 m ³
1 x 5.0 x 1.50 x 0.60				0.60	4.50 m ³
1 x 6.0 x 1.40 x 0.50				0.50	4.20 m ³
3 x 7.50 x 1.60 x 0.30				0.30	10.80 m ³

$$1 \times 3.0 \times 2.0 \times 0.50 = 3.00 \text{ m}^3$$

$$7 \text{ KM to } 9.01 \text{ KM}$$

$$2 \times 12.00 \times 1.20 + 2.10 \times 0.60 = 23.76 \text{ m}^3$$

$$\text{Total} = 101.11 \text{ m}^3$$

$$\frac{1716720}{1716720}$$

Continuation

P.T.

Continuation

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- *Madhepur*

Name of Road :- *Madhepur to Bheja via Bhit Bhagwanpur*

A. For Road

1. Damage Location Chainage :-
2. Damage Length :- *152.00*
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:- *Brick Bats*
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

B. For Bridge

1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-

Chauhan
30/04/22
Signature of JE/AE/EE

2036
20/4/22
BR

*photo & measurement not
match*
Ch
grade cut grade 's'

2
374
Signature
(Name of Inspection)