

F1D/R - 2021-2022

Schedule XLV-Form No. 134
Road From Khair School to Pirjahi

Executive Engineer

Rural Works Department

Works Division, Dharmapuri

DIVISION

Madhiefur

SUB-DIVISION

3135

MEASUREMENT BOOK

Name to work—

1

Situation of work—

Agency by which work is executed—

Date of measurement—

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
F.D.R.					
Name of work: Motorability					
(Road damaged by					
Flood from Khoir					
School) to Pirigahi					
For year-2021.					
Agency: Department					
Block: Block					
Madhepur					
Authority: at					
Ext. Eng. RWD					
(Wong) Jhangkar					
pur					
Received Measurement					
1. Providing and filling					
brick bats in Ditches /					
damaged embankment					
including cost of brick					
bats and labour all					
cont job as per spec					
location and direction					
of E.V.					

Continuation

P.T.O.

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
chainage					
700 to 1250					
1 x 15.0 x 2.40 + 2.80				0.15	5.85 m ³
1 x 10.0 x 2.40 + 2.10				0.22	6.19 m ³
1 x 10.0 x 2.40 + 1.10				0.225	6.19 m ³
1 x 7.0 x 2.10 + 2.80				0.15	2.57 m ³
1 x 20.0 x 1.40 + 2.80 + 3.10					10.95 m ³
				0.15 + 0.30	
1 x 5.0 x 0.60 + 0.80				0.30	1.05 m ³
1 x 7.0 x 0.80 + 0.60				0.60	2.94 m ³
1 x 9.0 x 2.80 + 3.20					
				0.15 + 0.30	6.08 m ³

1 x 20.0 x 3.75 + 4.10 + 3.10					
				1.10 + 0.70	78.84 m ³

17/06/2022					114.47 m ³
------------	--	--	--	--	-----------------------

p. T. Continuation

Scanned with CamScanner

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- *Madhepur*

Name of Road :- *Khoir School to Pajahi*

A. For Road

1. Damage Location Chainage :-
2. Damage Length :- *143.00 m*
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:- *Brick Bat*
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:- *97 m - 114.42 m*

B. For Bridge

1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-

ELW in progress
photo & measurement not match. Additional photo affected
gravel ✓, 04/06/22

Chaudhary
30/04/22
Signature of JE/AE/EE

30556
20/4/22
RR

374
Signature
(Name of Inspection)