

KOSHI CANAL BRIDGE TO CHOURA MALL (F.D.R.)

Schedule XLV-Form No. 134

Thar Tharpur

DIVISION

Thar Tharpur SUB-DIVISION
3089

MEASUREMENT BOOK

Name of Work—

Situation of Work—

Agency by which work is executed—

Date of Measurement—

No. and date of agreement

(These four lines should be repeated at the commencement
of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
CH--	F.P.R.				
Name of work--	Mortable of road				
	damaged road from				
	Mahadev Kand Jor Lawe				
	to Agothi Karmat Lawe				
	under Chambhraganj				
	to Nanochrunk R.E.O				
	Road near Bardegaon				
	Koshi Canal Tuberish				
	of chaura mad road				
	Potmarb road near				
	badmatai Lawe khole				
	F.P.R.				
Agency	Departmental				
Date of entry:-	10.5.22				
	work done				
	Measurement as per TS				
(2)	providing protection				
	road bath midstated				
	and damaged embank				
	met midstated				
	of bangle bath road				
	Continuation				

2
Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Labellar charge as per E/F					
CH - 525M	1x	25.70X	2.70X	0.75	52.04 M ³
H - 400M	1x	20.30X	3.75X	0.78	58.42 "
H - 250M.	1x	1.30X	2.10X	0.65	1.23 "
H H	1x	1.25X	0.60X	0.50	0.38 "
H H	1x	0.50X	0.40X	0.35	0.07 "
H H	1x	1.90X	2.60X	0.30	1.68 "
H 150M	1x	3.50X	2.00X	0.30	4.58 "
H - 125M	1x	15.00X	3.75X	0.43	93.91 "
H - 90M	1x	2.20X	1.80X	0.40	1.58 "
					143.06 M ³
					10.5122
					1.15
					1.05
					0.22

Continuation

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Jhanjharpur

Name of Road :- Constrn. of Road from Mahadeo Kant Jha House to Ayodhi Karmat House
Under charaujanjyoti Narour Chouk R.E.O loop under Koshi Canal to beside
of charaujanjyoti Primary school near yadunath.

A. For Road


1. Damage Location Chainage :- ch. 525, 480, 250, 150, 125 and 20m
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:- Brick Bats
 - ii. Equipment's/Tools being used in Restoration works:- Tractor, JCB
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:- VAB 60 m

B. For Bridge

1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-



Signature of JE/AE/EE



S
29/11/12

Signature
(Name of Inspection)