

BALTHI — PARAPUR

Measurement Book

Schedule XLV-Form No. 134

JHANSI PARPUR

DIVISION

MADHAPUR

SUB-DIVISION

2044

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Machhepur

Name of Road :- Balahi - Patwarpur

A. For Road


1. Damage Location Chainage :- 0.70 to 900 m
2. Damage Length :- 329.40 m
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:- Block ball
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:- 329.40 m - 221.04 m³

B. For Bridge


1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-


Signature of JE/AE/EE


20/4/22
R.R.


Signature
(Name of Inspection)