




ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

2021-22

FLOOD DAMAGED REPORT



MIDR T03 to Mahathi

CT	-	Samastipur	
IN	-	Dalsingh Sarai	
	-	Bibhutipur	
LENGTH OF ROAD	-	4.39	KM
COST OF PROJECT	-	0.94	Lac

PDR
YEAR (2021-2022)
GENERAL ABSTRACT OF COST

DISTRICT - SAMASTIPUR

CK [a] BIBHUTIPUR

OF ROAD - Repair of Road in MIDR T03 to Mahathi

NO	ITEM OF WORK	AMOUNT	
A	TOTAL COST OF CONSTRUCTION	Rs.	94542
	SUB TOTAL	Rs.	94542

Junior Engineer

RWD (W) Section, Bibhutipur

Assistant Engineer
RWD (W) Sub Division,
Bibhutipur

Executive Engineer
RWD, Works Division,
Dalsinghsarai

Sanctioned
Permissible Technical work approved for 94,548:00 say ninety four
thousand five hundred forty eight only including
C.P.C. 12% C.P. 10%.

dyr
10/12/21
T. A

10-12-21

बसीरब बसिबंका
शारीर शारं विचार
शारं संरक्ष, प्रबन्धोप

h
40
10-12-21

Site Photograph

Def Road:- MDR t03 to Mahathi
k- Bibhutipur

Dist- Samastipur



28/10/21

28/10/21
AEE

SUMMARY OF COST ESTIMATE FOR THE PROJECT

NAME OF ROAD :- Repair of Road in MIDR T03 to Mahathi

SAMASTIPUR

BIBHUTIPUR


NO	DESCRIPTION	AMOUNT LAKH
1	Hume Pipe	15644.250
	BRICK BAT	64867.824
	GSB	3159.000
	SUB TOTAL:-	83671.074
	12% GST on Total Amount:-	10040.529
	1% lab cess	836.711
	Total Cost (including GST and Labour Cess	94548.314


28/10/21

JE


28/11/21

A.E


02.12.21

EE

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Doleingaras

2. Name of Block – Bibhutipur

3. Name of Road/Bridge –

A. for Road

MDR T03 to Mahathi

1. Damage Location/Chainage : 0.75 km

2. Damage Length : 0.005 km

3. Nature of Damage : flood.

4. Details of Restoration Works :

i. Material being used in Restoration works : laying H.P. Pipe, Broken bricks, bricks

ii. Equipments/Tools being used in Restoration Works : tractor, Roller

iii. Procedure taken up in Restoration works :

iv. Restored Length : 0.005 km

B. for Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :

iv. Restored Length :

05/04/22
J.E.

05/04/22
A.E.

05/04/22
Executive Engineer,
R.W.D. Works Division,
Doleingaras

Work done at the
factory
05/04/22
Signature
(Name of Inspector)
E. B. T...
Rd work division