

Inspection Report of Flood Damage Work

Name of PU's :- RWD Works Division, Jhanjharpur

Name of Block :- Madhepur

Name of Road :- Kharik west kosi Bandh to Ratuar

A. For Road

1. Damage Location Chainage 200 to 400
2. Damage Length 69 meter 32m
3. Nature of Damage

4. Details of Restoration Works Brick Bat's

i. Materials being used in restoration works:- tractor

ii. Equipment's/Tools being used in Restoration works:-

iii. Procedure taken up in Restoration works:-

iv. Restored Length:- 69 meter

32m - 28.11m

B. For Bridge

1. Damage Location Chainage
2. Damage Length
3. Nature of Damage
4. Details of Restoration Works

i. Materials being used in restoration works:-

ii. Equipment's/Tools being used in Restoration works:-

iii. Procedure taken up in Restoration works:-

iv. Restored Length:-

C. Requirement Of New CD Bridges

i. Name of Road:-

ii. Location/ Chainage:-

iii. Type of CD Work/ Length required:-

Signature
19/5/22

Signature of JE/AE/EE

Signature
23/4/22
RR

Signature
09/06/22
gnde 's'

Signature
(Name of Inspection)

Schedule XLV-Form No. 134

west Kosi Bandh to

Ratua

FDR-21-22

Executive Engineer
Rural Works Department
Works Division, Jharkhand

DIVISION

MADHEPUR

SUB-DIVISION

3137

MEASUREMENT BOOK

Name of work—
 Situation of work—
 Agency by which work is executed—
 Date of measurement—
 No. and date of agreement.
 (These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
CH - F.D.R.					
Name of work - Notation					
of Road damage road					
from Kharik west					
Koti Bhand to Radpur					
Agency - Departmental					
Authority - Executive					
Engineer R.W.D. Dham-					
Tharapur					

Measurement					
① Providing and sitting					
Brick Batts and					
damaged embankment					
during coat brick soil					
and labour cess as					
per C/P					
1x7x	2.8	x0.30			5.88 m ³
1x8x	2.1	x0.30			5.04 m ³
1x5x	2.5	x0.30			3.75 m ³
1x12x	2.8	x0.40			13.44 m ³
1x16x	2.8	x0.40			28.11 m ³
1x17x	2.8	x0.40			

Continuation

[illegible]