

Inspection Report for Flood Damage Work

Date:- 01/12/2021

1. Name of PIUs- Executive Engineer, R.W.D, Works , Division, :- Manghauri Bakshi

2. Name of Block:- Navkothi

3. Name of Road/Bridge- Navkothi - se Rajakpur

A. For Road.

1. Damage Location/Chainage :- 1.05 to 1.10 km

2. Damage Length :- 50m

3. Nature of Damage :- due to heavy rain

4. Details of Restoration Works :-

i. Material being used in Restoration Works : Brick bat, Bamboo piling, empty cement bag filling with local sand

ii. Equipments/Tools being used in Restoration Works:

iii. Procedure taken up in Restoration Works :

iv. Restored Length : 50m

B. For Bridge N.A

1. Damage Location / Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration Works :

ii. Equipments/Tools being used in Restoration works :

iii. Procedure taken up in Restoration Works :

iv. Restored Length :

Wangdow fannal Sath's factory

Signature
01/12/21

A.E.

Signature
01/12/21

Executive Engineer,

R.W.D Works Division,

Signature
01/12/21

(Name of Inspector)

श्री ५ अचल, समस्तोपुर