

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, छपरा-1।

पत्रांक... 918 अनु... छपरा-1/दिनांक... 30.06.2022

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, छपरा-1

सेवा में,

नोडल पदाधिकारी (MR 3054)
ग्रामीण कार्य विभाग
पटना, बिहार

विषय :- नई अनुरक्षण नीति-2018 MR (3054) योजना के अंतर्गत पथ में कराये गये कार्य के विरुद्ध
आवंटन उपलब्ध कराने के संबंध में।


महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि नई अनुरक्षण नीति-2018 MR (3054)
योजना के अंतर्गत पथ में कराये गये कार्य के लिए संवेदक को भुगतान करने हेतु अधियाचना विहित प्रपत्र
में भरकर आवश्यक कार्यवाही हेतु समर्पित की जाती है।

अनु :- यथोक्त।

विश्वासभाजन


कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, छपरा-1।


30.06.2022

Name of Works Division:- Chapra-1


Maintenance Requisition Formate for Scheme Head- MR (3054) Ur

Road Details				AA Details										Agreement				
Sl. No.	Name of Raods	Batch No.	Project ID	Actual Date of Completion	Main Work Amount (in Lakh)	Maintenance Amount (in lakh)	Main Work Amount (in Lakh)	Agreement-1	Agreement-2	Agreement-3	Agreement-4	Agreement-5	Total Maintenance					
1	2	3	4	5	6	7	8	9	10	11	12	13	14					
1	KATOKHAR - MAHUI	RM/SA/C HA/19/0 011	31306302046	31/10/2020	68.585	32.372	68.585	2.59946	4.09814	9.92907	4.87933	10.8632	32.3692					
2	BANWAR - CHAMRAHIYA	RM/SA/C HA/19/0 011	31306302009	30/12/2020	145.874	72.774	145.874	6.14227	9.28886	21.9231	11.2756	24.1373	72.7672					
3	CHANAPUR - CHAPHUL	RM/SA/C HA/19/0 018	31306302023	1/12/2020	19.633	9.597	19.633	1.19769	1.64557	2.05324	2.06841	2.63161	9.59652					
4	MOHMADPUR - LALPUR	RM/SA/C HA/19/0 018	31306302062	1/12/2020	72.299	35.243	72.299	3.45498	4.74473	9.4207	5.96694	11.6561	35.2435					
5	MOHAMMADPUR - TIWARI TOLA (MOHAMMADPUR)	RM/SA/C HA/19/0 018	31306202114	19/11/2020	61.817	30.272	61.817	3.02927	4.16857	7.55214	5.24715	10.2748	30.2719					
Total -----					368.21	180.26	368.21	16.42	23.95	50.88	29.44	59.56	180.25					

der

Bihar Rural Road Maintenance Policy-2018

Actual Maintenance Expenditure											Current Maintenance Demand											Remarks
Length (in Km)	1st. Year Maintenance	2nd. Year Maintenance	3rd. Year Maintenance	4th Year Maintenance	5th Year Maintenance	Total Maintenance Expenditure	Length as per Bump Report	IRI As per bump Report	1st QTR Maintenance	2nd QTR Maintenance	3rd QTR Maintenance	4th QTR Maintenance	5th QTR Maintenance	6th QTR Maintenance	7th QTR Maintenance	Total						
15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32					
3.5	0.00000	0.000	0.000	0.000	0.000	0.000	3.5	2538	1.61845	1.61845	1.61845	1.61845	0.000	0.000	0.000	6.47380						
7.5	3.63835	0.000	0.000	0.000	0.000	0.000	7.5	2867	3.63835	3.63835	3.63835	0.000	0.000	0.000	0.000	10.91505						
1.141	0.47982	0.000	0.000	0.000	0.000	0.000	1.141	2604	0.47982	0.47982	0.47982	0.000	0.000	0.000	0.000	1.43946						
3.285	1.76217	0.000	0.000	0.000	0.000	0.000	3.285	2541	1.76217	1.76217	1.76217	0.000	0.000	0.000	0.000	5.28651						
2.903	0.00000	0.000	0.000	0.000	0.000	0.000	2.903	2529	1.51359	1.51359	1.51359	1.51359	0.000	0.000	0.000	6.05436						
18.33									9.01238	9.01238	9.01238	3.13204	0.00000	0.00000	0.00000	30.16918						


 Executive Engineer
 R.W.D. WORKS DIVISION
 Bihar
 30.06.2022

STANDRAD FORMAT FOR ROADS QUARTERLY STATEMENT

1	Name of the Road	MOHAMMADPUR - TIWARI TOLA (MOHAMMADPUR)		
2	Batch No.	RM/SA/CHA/19/0018		
3	Project ID	31306202114		
4	Total Length of Road (in Km)	2.9		
5	Length of Road to Meet Required Service Level [Completed length] (in Km) (1)	2.9		
6	No. of Total Quarter (ie 3 Months as a unit) in 5 years	20		
7	Ordinary Maintenance Cost as per Schedule (Agreement Amount for Maintenance) (in Lakh)	30.27189		
8	Quarterly Payment : 1/20 of Ordinary Maintenance Cost as per Schedule (in Lakh) (2)	1.51359		
Compliance Criteria	Standard Job Description	Non-Compliant		Reduction Payment (6) = (3) / (1) * (2) * (4)
		Length Non Compliant (3)	Weighted Value for Payment Reduction (%) (4)	
I	PAVED ROADS (CARRIAGEWAY)	0	60%	0.00000
II	SHOULDERS AND EMBANMENTS	0	10%	0.00000
III	CROSS DRAINAGE INCLUDING CULVERTS AND BRIDGES	0	15%	0.00000
IV	SIGNAGE AND ROAD SAFETY	0	10%	0.00000
V	VEGATAION		5%	0.00000
TOTAL PAYMENT REDUCTION FOR THE QUARTER (in Lakh) [5]				0.00000
TO BE PAID FOR THE QUARTER/DEMAND (in Lakh) [6]				1.51359

Date of inspection by E/I or his agent Prepared by
Contractor's self Control unit

Date

Signature of person inspecting road

Name and Designation of person inspecting road

(Signature)

Certify by E/I (signature) Date

Requisition :- Format for Scheme Head - M/R (3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division :- Chapra-1

Government of Bihar

OM01

Rural works Department

SUMMARY OF ORDINARY MAINTENANCE INSPECTION REPORT

Road From- MOHAMMADPUR - TIWARI TOLA

(MOHAMMADPUR)

Length of Road: 2.9 KM

Period : From.....

Inspector: A.E. RWD Sub Division, Manjhi

To: Executive Engineer
RWD Works Division Chapra-1

Date:

Position: A.E.

Standard Work item			Work		Units of work required in each kilometre										Comments
S No	Name	Units	1	2	3	4	5	6	7	8	9	10			
OM100 Sealed Pavement															
OM101	Pothole Patching	m2	Nil	Nil	Nil	Nil							No. Pothole found.		
OM102	Surface Depression and Rut Patching	m2	Nil	Nil	Nil	Nil							No Surface Depression and Rut Patching found		
OM103	Crack Sealing	Lm	Nil	Nil	Nil	Nil							No Crack Sealing found		
Surface Treatment															
OM104	(a) Loss of Aggregate (Surface Ravelling)	m2	Nil	Nil	Nil	Nil							No Loss of Aggregate (Surface Ravelling) found		
	(b) Bleeding/Flushing	m2	Nil	Nil	Nil	Nil							No Bleeding/Flushing Required		
	(c) Crocodile Cracking	m2	Nil	Nil	Nil	Nil							No Crocodile Cracking found		
OM105	Edge Repair	m2	Nil	Nil	Nil	Nil							No Edge Repair Required		
OM106	Dipsouts	m2	N/A	N/A	N/A	N/A									
OM107	Concrete Pavement	m3	N/A	N/A	N/A	N/A									
Other activities															
OM200 Shoulder															
OM201	Unsealed Shoulder	No											No Edge Drop off Required		
	(a) Edge Drop off	Lm	Nil	Nil	Nil	Nil							Defects rectified within stipulated time.		
	(b) Roughness, Scouring or Potholes	Lm	Nil	Nil	Nil	Nil							No Holding water found		
OM202	(c) Holding Water	Lm	Nil	Nil	Nil	Nil							No Embankment Repair Required		
	Embankment Repair	No	Nil	Nil	Nil	Nil							Defects rectified within stipulated time.		
	(Other Activities (Raincut))		3%	1%	2%	Nil									
OM 300 Drainage including culverts major															
OM301	Surface Drains & Verge	Lm	N/A	N/A	N/A	N/A							Not Required		

File H:\Satendra Upadhyay\MOHAMMADPUR - TWARI TOLA (MOHAMMADPUR) 44 25\25061523.xls. Section
Name of Customer :Satendra Upadhyay. Name of Work/ Road :MOHAMMADPUR - TWARI TOLA



Sumit
25.06.2012
ALTM

Sumit
25/6/12

Sumit
25/6/12
AE

Sumit
25/6/12
25/6/12
25/6/12

Scheme - New MR
Road Name- MOHAMMADPUR - TIWARI TOLA (MOHAMMADPUR)
Contractor Name - Satyendra Upadhyay

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event	$Y = 0 * X^2 + 1.000 * X + 415.2$
25/6/22	13:52:0	44	0.1	190	10.1	1900	2315	G	25.94086	84.489713	Normal	X = 2300
25/6/22	13:52:0	44	0.1	270	20.2	2700	3115	G	25.94095	84.48941	Culvert	Y = 2715
25/6/22	13:52:22	44	0.1	200	20.2	2000	2415	G	25.94148	84.488687	Speed Breaker	
25/6/22	13:52:22	44	0.1	70	40.4	700	1115	G	25.94155	84.487693	Normal	
25/6/22	13:53:0	44	0.1	140	30.3	1400	1815	G	25.94176	84.48648	Normal	(R) RURAL ROAD
25/6/22	13:53:0	44	0.1	250	30.3	2500	2915	G	25.94202	84.485453	Normal	Good
25/6/22	13:53:33	44	0.1	210	20.2	2100	2515	G	25.94214	84.48508	Speed Breaker	<4000
25/6/22	13:54:8	44	0.1	330	30.3	3300	3715	G	25.94253	84.483888	Normal	Average
25/6/22	13:54:43	44	0.1	90	40.4	900	1315	G	25.94282	84.482945	Normal	4001-5000
25/6/22	13:55:0	44	0.1	210	40.4	2100	2515	G	25.94306	84.48212	Normal	>5001
25/6/22	13:55:19	44	0.1	240	50.5	2400	2815	G	25.94335	84.48143	Normal	
25/6/22	13:55:19	44	0.1	160	40.4	1600	2015	G	25.94371	84.480622	Normal	
25/6/22	13:55:19	44	0.1	110	30.3	1100	1515	G	25.94392	84.479493	Normal	
25/6/22	13:56:0	44	0.1	250	30.3	2500	2915	G	25.94414	84.47847	Normal	
25/6/22	13:56:29	44	0.1	270	40.4	2700	3115	G	25.94432	84.477322	Normal	
25/6/22	13:56:29	44	0.1	170	30.3	1700	2115	G	25.94445	84.476615	Normal	
25/6/22	13:56:29	44	0.1	100	20.2	1000	1415	G	25.94472	84.47574	Normal	
25/6/22	13:56:29	44	0.1	310	30.3	3100	3515	G	25.94522	84.474512	Normal	
25/6/22	13:57:4	44	0.1	280	40.4	2800	3215	G	25.94553	84.47342	Normal	
25/6/22	13:57:4	44	0.1	250	50.5	2500	2915	G	25.94571	84.472743	Normal	
25/6/22	13:57:4	44	0.1	150	40.4	1500	1915	G	25.94599	84.47172	Normal	
25/6/22	13:57:39	44	0.1	350	30.3	3500	3915	G	25.94614	84.471127	Normal	
25/6/22	13:57:39	44	0.1	180	20.2	1800	2215	G	25.94627	84.470353	Culvert	
25/6/22	13:58:14	44	0.1	200	30.3	2000	2415	G	25.94554	84.470168	Normal	
25/6/22	13:58:14	44	0.1	320	20.2	3200	3615	G	25.94459	84.469998	Culvert	
25/6/22	13:58:14	44	0.1	190	30.3	1900	2315	G	25.94442	84.469123	Normal	
25/6/22	13:58:14	44	0.1	260	20.2	2600	3015	G	25.9446	84.468113	Culvert	
25/6/22	13:59:0	44	0.1	150	20.2	1500	1915	G	25.94483	84.46682	Normal	
25/6/22	13:59:25	44	0.1	230	10.1	2300	2715	G	25.94493	84.465858	Normal	
Total												
IRI Value												

Sum
85.04.2022
A/LM

8/28/22
20

8/28/22
20
AE