


Agency by which work is executed—



Date of Measurement—

No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/R-	Baswarida chowk se fci galambes tak pcc				
Block-	Dumra				
N/w-	Temporary restoration of flood damage road				
Authority-	E. E. Road(w) Div- Sitamarhi				
Measurement					
1> P/L of brick bat obtained from chimney — E/L.					
	30.00	4.00	0.60	=	72.00 m ³
	30.00	4.40	0.60	=	79.20 m ³
	15.00	4.20	0.65	=	40.95 m ³
	12.00	4.20	0.70	=	35.28 m ³
	Total Qty-				227.43 m ³
	less 20% for voids (-)				45.49 m ³
	Total Qty-				181.94 m ³
2> providing quarry material suitable for filling voids — E/L.					
	Taking 20% of brick bat Qty.				
	i.e. 227.43 X 0.20 =				45.49 m ³
CH 01/05/22 M  P. K. Singh NS					

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L	B.	D.	
Abstract of Cost					
P/R of brick bat obtained from chimney.					
Qty. vide TMB					
Item-1 Page-1	181.94m ³				
@ Rs. 1827.25/m ³				Rs.	332450=00
providing quarry material rubbish for filling voids					
EM.					
Qty. vide TMB					
Item-2 Page-1	45.49m ³				
@ Rs. 873.01/m ³				Rs.	39713=00
Total				Rs.	372163=00
 20/04/22 NK  20/04/22 NS  20/04/22					