

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/R- Bhairon Keshi - Mohanmalpur					
Block- Dumrae					
N/W- Temporary restoration of flood damage road					
Authority- E.E. Road(W) Div-					
Sitemashi					
Measurement					
P/L of brick bat obtained from chimney — E/I.					
$30.00 \times 4.30 \times 0.90 = 116.10 m^3$					
$30.00 \times (\frac{5.00 + 4.20}{2}) \times 0.90 = 124.20 m^3$					
$80.00 \times (\frac{5.00 + 4.00}{2}) \times 1.05 = 141.75 m^3$					
$23.00 \times (\frac{5.00 + 4.00}{2}) \times 0.80 = 82.80 m^3$					
Total Qty - 464.85m ³					
less 20% for voids - 92.97m ³					
Total Qty - 371.88m ³					
providing quarry material rubbish for filling the voids — E/I.					
Taking 20% of brick bat Qty.					
i.e., $464.85 \times 0.20 = 92.97 m^3$					

eh
01/08/22
K

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of Cost					
1) RL of brick bat obtained from chimney — E/S.					
Qty. vide TMB					
item-1	371.88 m ³				
Page-1					
@ Rs. 1827.25/m ³ — Rs 679518.00					
2) providing quarry material rockdash for filling voids — E/S.					
Qty. vide TMB					
item-2	92.97 m ³				
Page-1					
@ Rs. 873.01/m ³ — Rs. 81164.00					
Total Rs. 760682.00					
Abstract to - 760682.00					

CH
20/01/22
NS

CH
20/01/22
NS

C. & P.
20.01.22

Continuation