

Name of Work—

Situation of Work—

Agency by which work is executed—

Date of Measurement—

No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/R- Bhoainpur - Bhadar Road					
Block- Dumra					
N/W:- Temporary restoration of flood damage road					
Authority- E.E Road W. Div. Sitemarshi					
Measurement					
1) P/L of brick bat obtained from chimney — E/S.					
$20.00 \times \left(\frac{6.00 + 4.50}{2} \right) \times 0.70 = 73.50 \text{ m}^3$					
$20.00 \times \left(\frac{5.50 + 5.00}{2} \right) \times 0.72 = 75.60 \text{ m}^3$					
$20.00 \times \left(\frac{6.00 + 4.80}{2} \right) \times 0.90 = 97.20 \text{ m}^3$					
$15.00 \times 3.70 \times 0.75 = 41.63 \text{ m}^3$					
$5.20 \times 3.60 \times 0.60 = 11.23 \text{ m}^3$					
					Qty- 299.16 m ³
less 20% for voids - (-)					59.83 m ³
					Qty- 239.33 m ³
2) providing quarry material rubbish for filling voids — E/S.					
Taking 20% of brick bats					
Qty.					
i.e., $299.16 \times 0.20 =$					59.83 m ³

Continuation

eh
01/03/22
H

11/3/22
NS

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Abstract of Cost					
p/l of brick bat obtained from chimney — E/S.					
Qty. Vide TMB					
item-1				239.33m ³	
Page-1					
@ Rs. 1827.25/m ³					Rs. 437316=00
providing quarry material rubbish for filling voids — E/S.					
Qty. Vide TMB					
item-2				59.83m ³	
Page-1					
@ Rs. 873.00/m ³					Rs. 52232=00
= Total				Rs.	489548=00

20/04/22
AC

20/04/22
NS

20/04/22
NS