

P.W.D. PATH SAHANI CHOWK UMARI TO MAHPALIT LETHIMASAR

F.D.R. - 2021-2022

(F.D.R.)

Shedule XLV Form No. 134.

DIVISION

LAXI + ATIAUR.

SUB-DIVISION

Measurement Book

2073

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Lakhanpur

Name of Road :- PWD Path Sahni Chowk Umari to Mahadevi Lenin Nagar

A. For Road

1. Damage Location Chainage :- ch. 0 to 300, ch. 1000 to 1500 m
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:- Brick Bats.
 - ii. Equipment's/Tools being used in Restoration works:- Tractor, JCB,
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:- 189 + 2372

B. For Bridge

1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-

Signature of JE/AE/EE

Signature
(Name of Inspection)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	H.	
C.H. - F.D.R.					
Name of work - masonry work					
work done on wall					
sidewalk check on wall					
formwork on wall					
on wall F.D.R.					
Agency: Departmental					
Date of entry	30	4		2022	
(1) Provisioning and hiring					
brick batty masonry					
damaged embankment					
including cost of rubble					
batt and labour charge					
as per E/F					6.75
CH-0-300	1x	30.00x	$\frac{0.60+0.40}{2}$	0.45	13.50m ³
	1x	10.00x	$\frac{0.5+0.30}{2}$	0.45	1.80 m
1000-1500	1x	30.00x	3.75x	0.30	33.75 m
" "	1x	30.00x	3.75x	0.45	50.625 m
" "	1x	30.00x	3.75x	0.45	50.625 m
" "	1x	30.00x	3.75x	0.45	45.00 m
" "	1x	5.00x	$\frac{0.5+0.60}{2}$	$\frac{0.3+0.30}{2}$	0.6875 m
					189.2375
					189.2375

Continuation

AC

Scanned with CamScanner