

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, मुजफ्फरपुर पूर्वी-2

पत्रांक: 457 अनु०
प्रेषक,

मुज०/दिनांक: 17/02/22

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल मुजफ्फरपुर, पूर्वी-2

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव,
बिहार ग्रामीण पथ विकास अभिकरण,
बिहार, पटना।


विषय: बिहार ग्रामीण पथ अनुरक्षण नीति- 2018 अनुरक्षण के तहत स्वीकृत योजनाओं के विरुद्ध
आवंटन की मांग करने के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में वित्तीय वर्ष 2019-20 नई अनुरक्षण नीति अंतर्गत वित्तीय वर्ष
2020-21 में अनुरक्षण मद में व्यय हेतु संलग्न विवरणी के अनुसार 1.78984 (एक लाख अठत्तर हजार नौ
सौ चौरासी रुपया मात्र) रुपये का आवंटन उपलब्ध कराने की कृपा की जाये ताकि किये गये अनुरक्षण
कार्यों का भुगतान किया जा सके।

अनु०:- यथोक्त।

विश्वासभाजन



कार्यपालक अभियन्ता
ग्रामीण कार्य विभाग, कार्य प्रमंडल,
मुजफ्फरपुर पूर्वी-2

Maintenance Requisition Formate for Scheme Head MR 3054 Under Bhar Road Maintenance Policy-2018 (Initial Rectification and Surface General)

Road Details				Name of Work Division:- Muzaffarpur East-2										Actual Maintenance Expenditure										Current Maintenance Demand				Rema rks
Sl No	Road Name	Batch No	Project Id	Actual Date of Completion	Main work	Mainte nace Amount	Main Work Amount	Agreemen t 1	Agreemen t 2	Agreemen t 3	Agreemen t 4	Agreemen t 5	Total Maintenance	Length	1st year Main tance	2nd year Main tance	3rd year Main tance	4th year Main tance	5th year Main tance	Total Main tance expen diture	Longt has Bump Report 1st yer	IML As per Bump report	1st QTR Maintenance	2nd QTR Maintenance	3rd QTR Maintenance	4th QTR Maintenance	Total	
1	Susta B - Susta B	RNV MUZ	316720277	30-06-21	36.04	14.52	33.93	0.8649	1.69014	4.86341	2.18359	5.254	14.85599	1.74	0	0	0	0	0	0	1.74	2813.29	0.21621	-	-	-	0.21621	1st QTR
2	Kumhraul - Kumhraul	RNV MUZ	316720216	20-05-21	40.97	19.8	38.61	1.1354	2.27675	5.86692	2.86563	6.56498	18.70971	1.94	0	0	0	0	0	0	1.94	2510.42	0.28386	-	-	-	0.28386	1st QTR
3	Construction of Madhupatti to Mahurara Mandir jare wall Sadak ka Nirman	RNV MUZ	316720105	31-05-21	63.58	25.53	59.88	1.4298	3.06887	8.46952	3.74517	9.31351	26.0269	2.98	0	0	0	0	0	0	2.98	2448.24	0.35746	-	-	-	0.35746	1st QTR
4	SUSTA - SUSTA	RNV MUZ	3167200139	19-06-21	91.07	39.88	85.86	2.2641	4.84814	13.365	6.00085	14.2945	40.77251	4.70	0	0	0	0	0	0	4.70	2492.27	0.56603	-	-	-	0.56603	1st QTR
5	Kanta Purancha - Lakshmanag ar	RNV MUZ	31672002400	19-06-21	58.97	25.92	55.04	1.4651	3.14914	8.6787	3.90276	9.28848	26.48418	3.05	0	0	0	0	0	0	3.05	2943.07	0.36628	-	-	-	0.36628	1st QTR
				Total:-												1.78984												

Executive Engineer
RWD Works Division
Muzaffarpur East-2

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division :- Muzaffarpur East-II

Government of Bihar

OM01

Rural works Department

SUMMARY OF ORDINARY MAINTENANCE INSPECTION REPORT

Road From SUSTA - SUSTA

Length of Road: 4.7 KM

Period : From.....

Inspector: A.E RWD Sub Division, Gaighat

To: Executive Engineer
RWD Works Division Muzaffarpur East-2

Date: 17-02-2022

Position: A.E

Standard Work item										Work	Units of work required in each kilometre										Comments																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																							
S No	Name	Units	1	2	3	4	5	6	7	8	9	10																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																
OM100 Sealed Pavement																								No. Pothole found.																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																				
OM101	Pothole Patching	m2	Nil	Nil	Nil	Nil								No Surface Depression and Rut Patching found																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																														
OM102	Surface Depression and Rut Patching	m2	Nil	Nil	Nil	Nil								No Crack Sealing found																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																														
OM103	Crack Sealing	Lm	Nil	Nil	Nil	Nil																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																																						

Other activities (White Washing)	m2	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
OM 400 Vegetation																			
Grass Contorol																			
OM401 a) Roadside-General Tidy	Ha	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
b) Clear near Safety signs, kilometre posts and roadside furniture	Ha	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
Tree and shrub management	No	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
Cuting trees	No	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
Cuting Shrubs	No	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
Other activities (Trimming of Grass)	M2	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
OM1500 Safety Signage and Road																			Not Required
OM1501 Signs Maintenance	No	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
OM1502 Guard Stones	L.m	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Not Applicable
OM1503 Distance Stones	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Not Applicable
OM1504 Road Marking	m2	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
Other activities																			

Bidder

Appendix

Executive Engineer, Rural Work Department, Work Division, Muzaffarpur East 2

0 0.10.20.30.40.50.60.70.80.9 1 1.11.21.31.41.51.61.71.81.9 2 2.12.22.32.42.52.62.72.82.9 3 3.13.23.33.43.53.63.73.83.9 4 4.1

Distance * 1000 m

667

1667

2667

3667

UV
mm/
km

File : C:\Users\BRRDA9\Downloads\Susta to Susta.xls, Section No. 48, Eqn : $Y = 0 \cdot X^2 + 0.989 \cdot X - 13.58$
 Name of Customer : Ram Swarth Ray, Name of Work/ Road : Susta to Susta, Lab Job number :

Road Name::Susta to Susta

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	IRI in MM/KM	CATEGO RY	Latitude	Longitu de	Event	Y = 0 * X ^ 2 + 0.989 * X - 13.58	Average	Poor
10/1/22	11:51:12	48	0.1	240	0	2400	ROAD	26.1078	85.68606	Normal	X = 2600		
10/1/22	11:51:32	48	0.1	200	20.2	2000		26.10779	85.68705	Normal	Y = 2557		
10/1/22	11:51:52	48	0.1	260	20.2	2600		26.1078	85.68813	Normal			
10/1/22	11:52:0	48	0.1	170	20.2	1700		26.10784	85.68912	Bridge			
10/1/22	11:52:12	48	0.1	200	20.2	2000		26.10785	85.6901	Normal	(R) RURAL ROAD		
10/1/22	11:52:22	48	0.1	330	20.2	3300		26.1078	85.69113	Normal	Good		
10/1/22	11:52:52	48	0.1	330	20.2	3300		26.1077	85.69214	Normal	<4000	4001-5000	>5001
10/1/22	11:53:0	48	0.1	230	20.2	2300		26.10675	85.69207	Curve			
10/1/22	11:53:20	48	0.1	170	20.2	1700		26.10652	85.69305	Normal			
10/1/22	11:53:32	48	0.1	230	20.2	2300		26.10639	85.69401	Normal			
10/1/22	11:53:52	48	0.1	260	20.2	2600		26.10625	85.69502	Normal			
10/1/22	11:54:0	48	0.1	300	20.2	3000		26.10605	85.69601	Normal			
10/1/22	11:54:8	48	0.1	310	20.2	3100		26.10584	85.69702	Normal			
10/1/22	11:54:28	48	0.1	280	10.1	2800		26.10586	85.69798	Normal			
10/1/22	11:54:53	48	0.1	200	20.2	2000		26.10677	85.69818	Normal			
10/1/22	11:55:0	48	0.1	230	10.1	2300		26.10769	85.69825	Normal			
10/1/22	11:55:18	48	0.1	220	10.1	2200		26.10859	85.69833	Normal			
10/1/22	11:56:0	48	0.1	180	10.1	1800		26.10949	85.6985	Normal			
10/1/22	11:56:29	48	0.1	310	10.1	3100		26.1104	85.69843	Normal			
10/1/22	11:57:4	48	0.1	230	10.1	2300		26.1101	85.69874	Speed Breaker			
10/1/22	11:57:24	48	0.1	220	10.1	2200		26.11068	85.69955	Normal			
10/1/22	11:57:39	48	0.1	200	10.1	2000		26.11068	85.70056	Normal			
10/1/22	11:58:0	48	0.1	180	10.1	1800		26.11072	85.7016	Normal			
10/1/22	11:58:14	48	0.1	360	10.1	3600		26.1107	85.70261	Normal			
10/1/22	11:58:34	48	0.1	230	20.2	2300		26.11052	85.70355	Normal			
10/1/22	11:59:0	48	0.1	230	20.2	2300		26.11026	85.70455	Normal			
10/1/22	11:59:20	48	0.1	330	10.1	3300		26.11006	85.70547	Normal			
10/1/22	11:59:45	48	0.1	280	10.1	2800		26.11011	85.70655	Normal			
10/1/22	12:0:0	48	0.1	370	10.1	3700		26.11018	85.70749	Normal			
10/1/22	12:0:36	48	0.1	250	10.1	2500		26.11063	85.70833	Normal			
10/1/22	12:1:11	48	0.1	210	0	2100		26.11078	85.70911	Normal			
10/1/22	12:1:46	48	0.1	220	10.1	2200		26.11168	85.70912	Normal			
10/1/22	12:2:21	48	0.1	200	10.1	2000		26.11257	85.70926	Normal			
10/1/22	12:2:41	48	0.1	290	20.2	2900		26.11347	85.70931	Normal			
10/1/22	12:2:51	48	0.1	320	20.2	3200		26.11439	85.70944	Bridge			
10/1/22	12:3:0	48	0.1	290	10.1	2900		26.11529	85.7096	Normal			

Road Name:-Susta to Susta

Date	Time	Section	Length	Bumps	Speed	IRI in MM/KM	CATEGO RY	Latitude	Longitu de	Event				
10/1/22	12:3:32	48	0.1	200	10.1	2000	1964 G	26.11582	85.71022	Speed Breaker				
10/1/22	12:4:7	48	0.1	290	10.1	2900	2854 G	26.11584	85.71125	Normal				
10/1/22	12:4:17	48	0.1	310	10.1	3100	3052 G	26.11587	85.71224	Normal				
10/1/22	12:4:43	48	0.1	270	20.2	2700	2656 G	26.11593	85.7133	Normal				
10/1/22	12:5:0	48	0.1	260	10.1	2600	2557 G	26.11607	85.71428	Normal				
					Average:-	2492.268								

2021/11/11