

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, मुजफ्फरपुर पूर्वी-2

पत्रांक: 457 अउ
प्रेषक,

मुज0/दिनांक: 17-02-2022

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल मुजफ्फरपुर, पूर्वी-2
सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव,
बिहार ग्रामीण पथ विकास अभिकरण,
बिहार, पटना।


विषय: बिहार ग्रामीण पथ अनुरक्षण नीति- 2018 अनुरक्षण के तहत स्वीकृत योजनाओं के विरुद्ध
आवंटन की मांग करने के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में वित्तीय वर्ष 2019-20 नई अनुरक्षण नीति अंतर्गत वित्तीय वर्ष 2020-21 में अनुरक्षण मद में व्यय हेतु संलग्न विवरणी के अनुसार 6.34246 (छः लाख चौतीस हजार दो सौ छयालीस रूपया मात्र) रुपये का आवंटन उपलब्ध कराने की कृपा की जाये ताकि किये गये अनुरक्षण कार्यों का भुगतान किया जा सके।

अनु0:- यथोक्त।


विश्वासभाजन



कार्यपालक अभियंता
ग्रामीण कार्य विभाग, कार्य प्रमंडल,
मुजफ्फरपुर पूर्वी-2

Maintenance Regulation Formate for Scheme Head MR 2054 (Under Bihar Rural Road Maintenance Policy-2018 (Initial Certification and Surface Renewal))
Name of Works Division:- Muzaffarpur East-2

Maintenance Requirement Formate for Scheme Head M.R. 2054 Under Bihar Rural Road Maintenance Policy-2018 (Initial Identification and Surface Rowing)																																										
Road Details				AA Details										Agreement										Actual Maintenance Expenditure										Current Maintenance Demand for next Quarter								
Sl No	Road Name	Batch No	Project Id	Actual Date of Completion	Main work	Maine nce Amount	Main Work Amount	Agreement 1.1	Agreement 1.2	Agreement 1.3	Agreement 1.4	Agreement 1.5	Total Estimate	Length	1st year	2nd year	3rd year	4th year	5th year	Total	Longt	1301 As per Bidding Report	1st QTR	2nd QTR	3rd QTR	4th QTR	Total	Remarks														
1	Susta II - Susta II	RNV/ MU/ 2000/ 14	310720219	30-06-21	36.04	14.52	33.93	0.8649	1.69014	4.86341	2.18359	5.254	14.85599	1.74	0	0	0	0	0	0	1.74	2813.29	0.742380	-	-	-	-	0.742380	1st QTR													
2	Kumbhant - Kumbhant	RNV/ MU/ 2000/ 14	310720245	20-05-21	40.97	19.8	38.61	1.1351	2.27675	5.86692	2.86563	6.56498	18.70971	1.94	0	0	0	0	0	0	1.94	2510.42	0.935486	-	-	-	-	0.935486	1st QTR													
3	Construction of Madhupatti to Mahurara Mandir lane wall Sadaa ka Nirman	RNV/ MU/ 2000/ 14	310720285	31-05-21	63.58	25.53	59.86	1.4298	3.06857	8.46952	3.74517	9.31351	26.0269	2.98	0	0	0	0	0	0	2.98	2448.24	1.391345	-	-	-	-	1.391345	1st QTR													
4	SUSTA - SUSTA	RNV/ MU/ 2000/ 14	NEA2100239	19-06-21	91.07	39.88	85.86	2.2641	4.84814	13.365	6.00085	14.2945	40.77251	4.70	0	0	0	0	0	0	4.70	2492.27	2.038626	-	-	-	-	2.038626	1st QTR													
5	Karla Pirauha - Lakshmanpur	RNV/ MU/ 2000/ 14	NEA2100240	19-06-21	58.97	25.92	55.64	1.4651	3.14914	8.6797	3.90276	9.28848	26.48418	3.05	0	0	0	0	0	0	3.05	2943.07	1.324209	-	-	-	-	1.324209	1st QTR													
Total:-																																6.34246										


 Executive Engineer
 RWD Works Division
 Muzaffarpur East-2

Requisition Form for Scheme Head - MR (3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Name of Works Division :- Muzaffarpur East-II

Government of Bihar

OM01

Rural works Department

SUMMARY OF ORDINARY MAINTENANCE INSPECTION REPORT

Road From Construction of Madhupatti to Mahurara Mandir
jane wai Sadak ka Nirman
Length of Road: 2.98 KM
Period : From.....
Inspector: A.E RWD Sub Division, Gaighat

To: Executive Engineer
RWD Works Division Muzaffarpur East-2
Position: A.E

Date: 17-02-2022

Standard Work item										Units of work required in each kilometre										Comments			
S No	Name	Work Units	1	2	3	4	5	6	7	8	9	10											
OM100 Sealed Pavement																							
OM101	Pothole Patching	m2	Nil	Nil	Nil	Nil							No Pothole found										
OM102	Surface Depression and Rut Patching	m2	Nil	Nil	Nil	Nil							No Surface Depression and Rut Patching found										
OM103	Crack Sealing	Lm	Nil	Nil	Nil	Nil							No Crack Sealing found										
Surface Treatment																							
OM104	(a) Loss of Aggregate (Surface Ravelling)	m2	Nil	Nil	Nil	Nil							No Loss of Aggregate (Surface Ravelling) found										
	(b) Bleeding/Flushing	m2	Nil	Nil	Nil	Nil							No Bleeding/Flushing Required										
	(c) Crocodile Cracking	m2	Nil	Nil	Nil	Nil							No Crocodile Cracking found										
OM105	Edge Repair	m2	Nil	Nil	Nil	Nil							No Edge Repair Required										
OM106	Digouts	m2	N/A	N/A	N/A	N/A																	
OM107	Concrete Pavement	m3	N/A	N/A	N/A	N/A																	
Other activities											Lm												
OM200 Shoulder																							
OM201	Unsealed Shoulder	No											No Edge Drop off Required										
	(a) Edge Drop off	Lm	Nil	Nil	Nil	Nil																	
	(b) Roughness, Scouring or Potholes	Lm	Nil	2%	4%	Nil							Defects rectified within stipulated time										
	(c) Holding Water	Lm	Nil	Nil	Nil	Nil							No Holding water found										
OM202	Embankment Repair	No	Nil	Nil	Nil	Nil							No Embankment Repair Required										
	Other Activities (Raincut)		4%	3%	2%								Defects rectified within stipulated time										
OM 300 Drainage including culverts major																							
OM301	Surface Drains & Verge	Lm	N/A	N/A	N/A	N/A							Not Required										
OM302	Culvert Cleaning	Lm											Culvert maintain within stipulated time										
OM303	Culvert and Pit repair	m2	Nil	Nil	Nil	Nil							Not Required										

Other activities (White Washing)	m2	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
OM 400 Vegetation																			
Grass Contorol																			
OM401																			
a) Roadside-General Tidy	Ha	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
b) Clear near Safety signs, kilometre posts and roadside furniture	Ha	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
Tree and shrub management	No	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
Cutting trees	No	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
Cutting Shrubs	No	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
Other activities (Trimming of Grass)	M2	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
OM500																			Not Required
Safety Signage and Road																			Not Required
OM501																			Not Required
Signs Maintenance	No	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
OM502																			Not Applicable
Guard Stones	Lm	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Not Applicable
OM503																			Not Applicable
Distance Stones	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Not Applicable
OM504																			Not Required
Road Marking	m2	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Not Required
Other activities																			

27/11/2022

Bidder

27/11/2022

DE.

Appendix


27/11/2022

DE.

Executive Engineer, Rural Work Department, Work Division, Muzaffarpur East 2

27/11/2022

File : C:\Users\BR\Downloads\Construction of Madhurpatti to Mahurara Mundir jone wali Sadak ke Nirman.xls,
 Name of Customer : Ram Swarth Ray, Name of Work/ Road Construction of Madhurpatti to Mahurara Mundir jone



25/11/17

Road Name:-Construction of Madhupatti to Mahurara Mandir jame wali Sadak ke Nirman														
Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	IRI in MM/KM	TEGORY	Latitude	Longitude	Event	y = 0 * X ^ 2 + 0.989 * X - 13.58			
10/1/22	10:36:44	46	0.1	230	0	2300	ROAD	26.13412	85.68808	Normal	X = 1700			
10/1/22	10:37:0	46	0.1	270	20.2	2700	2656 G	26.13371	85.68896	Normal	Y = 1667			
10/1/22	10:37:19	46	0.1	250	20.2	2500	2458 G	26.13336	85.6899	Normal				
10/1/22	10:37:19	46	0.1	240	20.2	2400	2360 G	26.13319	85.69093	Normal				
10/1/22	10:38:0	46	0.1	210	20.2	2100	2063 G	26.1328	85.69178	Curve	(R)RURAL ROAD			
10/1/22	10:38:0	46	0.1	240	20.2	2400	2360 G	26.13302	85.69266	Normal	Good	Average	Poor	
10/1/22	10:38:30	46	0.1	320	20.2	3200	3151 G	26.13289	85.69367	Normal	<4000	4001-5000	>5001	
10/1/22	10:38:30	46	0.1	350	10.1	3500	3447 G	26.13273	85.69466	Normal				
10/1/22	10:38:30	46	0.1	290	20.2	2900	2854 G	26.13214	85.695	Normal				
10/1/22	10:39:5	46	0.1	290	20.2	2900	2854 G	26.13124	85.6948	Normal				
10/1/22	10:39:5	46	0.1	320	20.2	3200	3151 G	26.13044	85.69498	Normal				
10/1/22	10:39:41	46	0.1	340	20.2	3400	3349 G	26.13037	85.69601	Normal				
10/1/22	10:39:41	46	0.1	310	20.2	3100	3052 G	26.13037	85.69704	Normal				
10/1/22	10:40:0	46	0.1	310	20.2	3100	3052 G	26.13032	85.69803	Normal				
10/1/22	10:40:16	46	0.1	270	20.2	2700	2656 G	26.1303	85.69904	Normal				
10/1/22	10:40:16	46	0.1	170	20.2	1700	1667 G	26.13027	85.7001	Normal				
10/1/22	10:41:0	46	0.1	160	20.2	1600	1568 G	26.13027	85.70111	Normal				
10/1/22	10:41:0	46	0.1	240	20.2	2400	2360 G	26.13027	85.70212	Normal				
10/1/22	10:41:26	46	0.1	310	10.1	3100	3052 G	26.13022	85.70318	Normal				
10/1/22	10:41:26	46	0.1	170	10.1	1700	1667 G	26.13013	85.70414	Normal				
10/1/22	10:42:2	46	0.1	350	10.1	3500	3447 G	26.13059	85.70498	Normal				
10/1/22	10:42:37	46	0.1	240	10.1	2400	2360 G	26.13119	85.70574	Normal				
10/1/22	10:43:12	46	0.1	220	0	2200	2162 G	26.13202	85.70614	Normal				
10/1/22	10:43:47	46	0.1	140	10.1	1400	1371 G	26.13291	85.70633	Normal				
10/1/22	10:44:23	46	0.1	180	10.1	1800	1766 G	26.1336	85.70684	Normal				
10/1/22	10:45:0	46	0.1	150	0	1500	1469 G	26.13434	85.70724	Normal				
10/1/22	10:47:54	46	0.1	200	0	2000	1964 G	26.134	85.70689	Normal				
10/1/22	10:48:30	46	0.1	280	10.1	2800	2755 G	26.13321	85.70653	Normal				
10/1/22	10:49:0	46	0.1	170	10.1	1700	1667 G	26.13239	85.70623	Normal				
Average:-							2448.241							

20/1/22